

David J. Johnson Director Service Engineering Operations Ford Customer Service Division Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

January 14, 2022

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD -

Safety Recall 22S01

Certain 2021 Model Year Super Duty and F-650/F-750 Vehicles

Equipped with a 6.7L Power Stroke Diesel Engine

Secondary Fuel Filter Leak

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates	
Super Duty	2021	Kentucky Truck	December 1, 2020 through January 8, 2021	
		Ohio Assembly	December 1, 2020 through January 7, 2021	
F-650/F-750	2021	Ohio Assembly	December 1, 2020 through December 22, 2020	

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In some of the affected vehicles, the secondary engine mounted fuel filter may have a void located on the top center portion of the filter housing and may progress to a pinhole leak. Vehicles with a pinhole leak may exhibit a noticeable fuel smell, a visible fuel leak, and/or an illuminated check engine light. A fuel leak in the presence of an ignition source may increase the risk of fire and injury.

SERVICE ACTION

Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to replace both primary and secondary fuel filters. This service must be performed on all affected vehicles at no charge to the vehicle owner.

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters are expected to be mailed the week of January 24, 2022. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

ATTACHMENTS

Attachment I: Administrative Information

Attachment II: Labor Allowances and Parts Ordering Information

Attachment III: Technical Information

Owner Notification Letters

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

David J. Johnson

Certain 2021 Model Year Super Duty and F-650/F-750 Vehicles Equipped with a 6.7L Power Stroke Diesel Engine Secondary Fuel Filter Leak

OASIS ACTIVATION

OASIS will be activated on January 14, 2022.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will be available through https://web.fsavinlists.dealerconnection.com on January 14, 2022. Owner names and addresses will be available by February 11, 2022.

NOTE: Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

SOLD VEHICLES

- Ford has not issued instructions to stop selling/delivering or driving used vehicles under this safety recall. Owners should contact their dealer for an appointment to have their vehicles remedied as soon as practicable. Owners can continue to safely drive their vehicles.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

Certain 2021 Model Year Super Duty and F-650/F-750 Vehicles Equipped with a 6.7L Power Stroke Diesel Engine Secondary Fuel Filter Leak

OWNER REFUNDS

Refunds are not approved for this program.

RENTAL VEHICLES

Rental vehicles are not approved for this program.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
 - o Ford vehicles 3 years or 36,000 miles
 - F-650/F-750 trucks 2 years, regardless of miles driven
- For vehicles outside new vehicle bumper-to-bumper warranty coverage, submit an Approval Request to the SSSC Web Contact Site prior to completing the repair.

CLAIMS PREPARATION AND SUBMISSION

- Claim Entry: Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims, select claim type 31: Field Service Action. The FSA number (22S01) is the sub code.
 - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- Related Damage/Additional labor and/or parts: Must be claimed as Related Damage on a separate repair line from the FSA with same claim type and sub code as described in Claim Entry above.
 - **IMPORTANT:** Click the Related Damage Indicator radio button.
- **Towing:** Towing may be required. Please use Roadside Assistance for vehicle towing.

Certain 2021 Model Year Super Duty and F-650/F-750 Vehicles Equipped with a 6.7L Power Stroke Diesel Engine Secondary Fuel Filter Leak

LABOR ALLOWANCES

Description	Labor Operation	Labor Time				
FOR SUPER DUTY VEHICLES ONLY						
Replace Both Primary and Secondary Fuel Filters						
- Only 1 labor operation can be claimed per vehicle. Cannot be claimed with 22S01C	22S01B	0.8 Hour(s)				
FOR F-650/F-750 VEHICLES ONLY						
Replace Both Primary and Secondary Fuel Filters						
- Only 1 labor operation can be claimed per vehicle. Cannot be claimed with 22S01B	22S01C	0.8 Hour(s)				

PARTS REQUIREMENTS / ORDERING INFORMATION

SSSC Web Contact Site:

To place an order, submit a VIN-specific Part Order contact via the SSSC Web Contact Site.

Part Number	Description	Order Quantity	Claim Quantity
LC3Z-9N184-A	For Super Duty Vehicles ONLY – Fuel Filter Kit (Kit contains both Primary and Secondary Fuel Filters)	1	1
HC4Z-9N184-B	For F-650/F-750 Vehicles ONLY – Fuel Filter Kit (Kit contains both Primary and Secondary Filters)	1	1

Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering resumes.

DEALER PRICE

For latest prices, refer to DOES II.

PARTS RETENTION, RETURN, & SCRAPPING

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES. If a replaced part receives a scrap disposition, the part must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Certain 2021 Model Year Super Duty and F-650/F-750 Vehicles Equipped with a 6.7L Power Stroke Diesel Engine Secondary Fuel Filter Leak

REPLACED FSA PARTS INSPECTION AND SIGN OFF

Effective March 1st, 2021 all parts replaced as part of an FSA repair with a repair order open date of March 1st, 2021 or later must be inspected and signed off on the repair order by a member of your dealers fixed operations management team or an employee the task has been delegated to. If the task is to be delegated to a non-management employee, the employee needs to be someone other than the technician who completed the repair and needs to understand the importance of completing this task consistently and accurately.

- All parts replaced as part of an FSA repair should be returned to the parts department following the Warranty Parts Retention and Return Policies.
- Inspect the replaced parts to verify the FSA repair was completed.
- If the FSA repair is found to be complete, the designated employee signs the repair order line or parts return stamp area (electronic or hand signed) for the FSA repair indicating the parts were inspected and validated to have been replaced.
- After the parts have been inspected, they should be handled based on the guidance in the parts status report in the Online Warranty System (Hold, Return, CORE, Scrap, etc.).
- This process is subject to review during warranty audits for FSA repairs with a repair order open date of March 1st, 2021 or later. Any eligible FSA claims requiring parts replacement, found not to have been inspected and signed off during a warranty audit will be subject to chargeback and consideration for enrollment into the Dealer Incomplete Recall Repair Process.

Note: Other approvals (electronic or handwritten) for add-on repair lines, dealer owned vehicle repairs, and repeat repairs do not qualify as FSA parts inspection approvals. The post repair FSA parts inspection process (electronic or handwritten) is independent from other warranty approval requirements. The approval by the designated employee implies that the FSA parts were found to be replaced and must be able to be clearly identified on the Repair Order. If multiple FSA's require approval on a single Repair Order, each applicable occurrence will require individual post repair approval by the designated employee.

CERTAIN 2021 MODEL YEAR SUPER DUTY AND F-650/F-750 VEHICLES EQUIPPED WITH A 6.7L POWER STROKE DIESEL ENGINE — SECONDARY FUEL FILTER LEAK

SUPER DUTY SERVICE PROCEDURE

NOTE: Both fuel filters are to be replaced under this recall.

1. For Super Duty Trucks please follow the Workshop Manual (WSM) procedures in Section 310-01C. See Figure 1 for location reference and filter description.




FIGURE 1

IMPORTANT NOTE: Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall. Unless a part is requested to be returned to Ford, all parts replaced under this FSA must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Refer to the Parts Retention, Return, & Scrapping section of the FSA dealer bulletin for further information.

F-650/F-750 SERVICE PROCEDURE

NOTE: Both fuel filters are to be replaced under this recall.

NOTE: Images in WSM may not represent what is in vehicle please see Figure 2 for correct image.

1. For F-650/F-750 vehicles please follow the WSM procedures in Section 310-01A. See Figure 2 for location reference and filter description.




FIGURE 2

IMPORTANT NOTE: Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall. Unless a part is requested to be returned to Ford, all parts replaced under this FSA must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Refer to the Parts Retention, Return, & Scrapping section of the FSA dealer bulletin for further information.