



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

January 25, 2022

Mr. Will Swindell  
Senior Engineer  
Nissan North America, Inc.  
P.O. Box 685001  
Franklin, TN 37068

NEF-107SS  
22V-024

**Subject:** Electrical Connector Under Dash May Corrode

Dear Mr. Swindell:

This letter serves to acknowledge Nissan North America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

NISSAN/ROGUE/2014-2016

**Mfr's Report Date:** January 21, 2022

**NHTSA Campaign Number:** 22V-024

**Components:**

ELECTRICAL SYSTEM:WIRING:INTERIOR/UNDER DASH

**Potential Number of Units Affected:** 688,946

**Problem Description:**

Nissan North America, Inc. (Nissan) is recalling certain 2014-2016 Rogue vehicles. The electrical connector for the under dash harness may corrode due to water and salt intrusion from the driver's side foot well.

**Consequence:**

Corrosion in the electrical connector can result in power window/seat failure, all-wheel-drive warning light illumination, battery drainage, and electrical connector damage that increases the risk of a fire.

**Remedy:**

The remedy is currently under development. Interim owner notification letters informing owners of the safety risk are expected to be mailed March 2, 2022. A second notice will be mailed once the remedy becomes available. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is R21B9.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please ensure the following requirements are met:

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the dash side harness. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Nissan North America, Inc.'s contact for this recall will be Sarah Shiver who may be reached by email at [sarah.shiver@dot.gov](mailto:sarah.shiver@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement