

# ANA4 Stop Delivery - Checking wiring harness routing of rear seat belt buckle and rework if necessary

---

## ANA4 Stop Delivery - Checking wiring harness routing of rear seat belt buckle and rework if necessary

ID Number	ANA4
Models	Taycan (Y1A/Y1B/Y1C)
Model Years	2020-2022
VIN list	Attached
Issue Description	On the affected vehicles, there is a possibility of an issue with the passenger side rear seat inboard LATCH anchor that will require an inspection.
What Should Dealers Do?	<b>Please do not deliver the subject vehicles until remedy instructions are distributed.</b>
What will Porsche Do?	Additional information will be provided as soon as possible.
TI Number	TI to be released at a later date.
Customer Reactive Statement	Pending

### Important information

**IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.**