

 Tesla, Inc. Service Bulletin		<h2>Replace Curtain Airbag</h2>	
SB-22-20-001 February 28, 2022			
Classification		Section/Group	Mobile Service
Recall Bulletin		20 - Safety and Restraint	Can Perform (where permitted)
Model Year	Model	Country/Region	Build Location
2021 - 2022	Model S	United States	Fremont
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Model S vehicles were equipped with a curtain airbag that may not have been assembled to specifications.

Correction

Replace the LH or RH curtain airbag as indicated within the VIN Lookup Table.

Correction Description	Correction	Time
Replace LH Curtain Airbag	S012220001	0.60
Replace RH Curtain Airbag	S022220001	0.60

Part Number	Description	Quantity
Parts Required 1608265-00-B	CURTAIN AIRBAG ASSEMBLY - LEFT HAND	0-1
1608266-00-B	or CURTAIN AIRBAG ASSEMBLY - RIGHT HAND	0-1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

1. Locate the VIN in the table below to determine which curtain airbag to replace (Figure 1).

VIN	Replace LH/RH Curtain Airbag
5YJSA1E59MF446817	Replace LH curtain airbag only
5YJSA1E56NF469439	Replace LH curtain airbag only
5YJSA1E6XMF435740	Replace RH curtain airbag only
5YJSA1E54MF435630	Replace RH curtain airbag only
5YJSA1E55MF442215	Replace RH curtain airbag only
5YJSA1E56NF464984	Replace RH curtain airbag only
5YJSA1E54NF467303	Replace RH curtain airbag only
5YJSA1E58NF470768	Replace RH curtain airbag only
5YJSA1E55NF470792	Replace RH curtain airbag only

Figure 1 – VIN Lookup Table

2. Replace the affected curtain airbag (refer to Service Manual procedure [20012002](#)).