

CORRECTED - Advance Notice – <u>Safety Recall 93O2 / Flexible Printed Circuit Solder –</u> <u>HV Battery</u>

This notice is for:	 ✓ Dealer P ✓ General ✓ Sales Ma 	Manager	✓ Parts	ice Manager Manager ice Consultant	✓ Warranty✓ Technicia	y Administrator ans	
Date:	April 08, 2022						
Issue:	Specific soldering points on the flexible printed circuit assembled (FPCA) inside the HV battery may not establish a reliable connection due to manufacturing issues. Unreliable connections inside the HV battery may lead to breakdowns or stalling while driving in the field. This can lead to a crash without warning.						
Precautions:	If this issue is present in the vehicle, the driver would be alerted by a message appearing in the instrument panel warning about an issue in the high voltage system. Should this occur, owners are advised to make an appointment with their authorized Volkswagen dealer without delay to have the vehicle diagnosed/repaired.						
Repair:	 REPAIR NOT YET AVAILABLE Check daily campaign open inventory report or OMD for affected vehicles in inventory. 						
Affected Vehicles	Country	Beginning Model Year	Ending Model Year	Vehio	cle	Vehicle Count	
Affected Vehicles	Country USA	Model	Model	Vehic ID4			
Affected Vehicles Notes:	USA *Counts reflect screen in Elsa of campaign inqui IMPORTAN New Vehicles motor vehicle this notificat	Model Year 2021 It overall population the day of repairing & verification T REMINDER: Note in Dealer Inversion of any new of ion under a sa	Model Year 2021 ion; some vehico <u>ir</u> to verify that source. /EHICLES AF entory: It is a r used item of le or lease un		been repaired. Cloair under this action TY & COMPLIAN al law for a deal ipment (includin oncompliance is	Count 351 heck Campaigns/Ad heck Campaigns/Ad h	valid new i by aw,

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.