



*A Tradition of Quality. Since 1905*

March 30, 2022

Important Safety Recall Information – Recall Number: 22V-172

Marion Body Works was notified of a recall issued by Navistar which relates to motor vehicle safety exists in certain 2018 and 2019 Durastar and WorStar model trucks and certain 2019 and 2020 HV and MV series trucks build 01/12/2017 thru 09/24/2019 with feature code 12VXT (Engine Speed Control; Electronic, Stationary, Variable Speed) or 12VXU (Engine Speed Control for PTO; Electronic, Stationary Pre-Set, Two Speed Settings).

**Noncompliance Description:**

On certain trucks equipped with an automatic transmission, if the automatic transmission is still in drive or reverse position and the stationary PTO switch is engaged, the engine RPM will ramp up and may overcome parking brake hold capability resulting in possible vehicle movement.

Unexpected movement of the truck can increase the risk of a crash resulting in property damage or personal injury.

This chassis is still under the possession of Marion Body Works.

As of March 30, 2022 this chassis has been repaired per the instructions provided by Navistar.

Sincerely,

A handwritten signature in black ink, appearing to read 'Rachel Heineman', written in a cursive style.

Rachel Heineman  
Quality & Continuous Improvement Manager

