

Part 573 Safety Recall Report

22V-201

Manufacturer Name : Lance Camper Manufacturing, Corp.**Submission Date :** APR 07, 2022**NHTSA Recall No. :** 22V-201**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :****Manufacturer Name :** Lance Camper Manufacturing, Corp.**Number of potentially involved :** 18**Address :** 43120 Venture Street**Estimated percentage with defect :** 100 %

Lancaster CA 93535

Company phone : 661-949-3322**Vehicle Information :****Vehicle 1 :** 2022-2022 Lance 1685, 1985, 1995, 2185, 2445**Vehicle Type :** TRAILERS**Body Style :****Power Train :** NR

Descriptive Information : discovered on the line on new 2022 units with the Truma water heater option.
all units built within the dates are effected
18 units effected

Production Dates : OCT 05, 2021 - FEB 26, 2022**VIN Range 1 : Begin :** 56YTT2420NL332523 **End :** 56YTT2127NL333141 ☒ Not sequential**Description of Defect :**

Description of the Defect : Truma water heater, DATA CABLE IS ROUTED THROUGH THE COLD WATER INLET IN THE REAR OF THE WATER HEATER AND COULD REST AGAINST BURNER BOX

FMVSS 1 : NR**FMVSS 2 :** NR**Description of the Safety Risk :** DATA CABLE SHORT POSSIBLE FIRE**Description of the Cause :** DATA CABLE MELTED FROM BURNER BOX

Identification of Any Warning that can Occur : WATER HEATER CONTROL PANEL AND WATER HEATER INOPERERTIBLE.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

IDENTIFIED ON THE PRODUCTION LINE THAT THE DATA CABLE WAS NOT BEING INSTALLED PER THE MANUFACTURER SPECIFACATIONS.

Description of Remedy :

Description of Remedy Program : REROUTE THE DATA CABLE FROM THE COLD WATER INLET AND REROUTE PER MANUFACTURER SPECIFACATIONS.
LANCE WILL REIMBURSE DEALER THROUGH A WARRANTY CLAIM.

NOTE:Customers who have had this remedy completed before this recall are eligible for reimbursement, contact Lance customer service (661) 949-3322

How Remedy Component Differs from Recalled Component : INSTALLATION ERROR.

Identify How/When Recall Condition was Corrected in Production : ROUTED THE DATA CABLE PER THE MANUFACTURER SPECIFICATIONS

Recall Schedule :

Description of Recall Schedule : MAIL OUT DEALER AND CUSTOMER LETTERS

Planned Dealer Notification Date : MAY 27, 2022 - JUN 30, 2022

Planned Owner Notification Date : MAY 27, 2022 - JUN 30, 2022

* NR - Not Reported