



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

April 5, 2022

Mr. Charles Smart  
Head of Claims Management Dept  
Triumph Motorcycles America, Ltd.  
Normandy Way  
Hinckley 1

NEF-107SS  
22V-207

**Subject:** Rear Brake Disc Bolts May Loosen

Dear Mr. Smart:

This letter serves to acknowledge Triumph Motorcycles America, Ltd.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

TRIUMPH/SPEED TRIPLE RR/2022  
TRIUMPH/SPEED TRIPLE RS/2022

**Mfr's Report Date:** March 31, 2022

**NHTSA Campaign Number:** 22V-207

**Components:**

SERVICE BRAKES, HYDRAULIC:CRITICAL FASTENERS

**Potential Number of Units Affected:** 910

**Problem Description:**

Triumph Motorcycles America, Ltd. (Triumph) is recalling certain 2022 Speed Triple RS and Speed Triple RR motorcycles. The rear brake disc bolts may loosen.

**Consequence:**

A loose rear brake disc bolt may contact other components, preventing the wheel from rotating freely and increasing the risk of a crash.

**Remedy:**

Dealers will replace the rear brake disc bolts, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Triumph customer service at 1-678-854-2010. Triumph's number for this recall is SRAN 596.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

We have received Triumph's proposed owner notification letter and have approved it for distribution.



**Please ensure the following requirements are met:**

As required in Part 573.6, please amend the chronology to provide the test date when the safety defect was discovered, a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Triumph Motorcycles America, Ltd.'s contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is fluid and cursive, with a checkmark-like flourish at the end.

Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement