

U.S. Department of Transportation

National Highway Traffic Safety Administration

April 12, 2022

Ms. Pascale Belanger Volvo Bus Corporation 260 Banker road Plattsburgh, NY 12901 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107SS 22V-222

Subject: Alternator Belt May Overheat Seized Bearing

Dear Ms. Belanger:

This letter serves to acknowledge Volvo Bus Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

VOLVO BUS/9700/2020

Mfr's Report Date: April 6, 2022

NHTSA Campaign Number: 22V-222

Components:

ELECTRICAL SYSTEM:ALTERNATOR/GENERATOR/REGULATOR ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

Potential Number of Units Affected: 47

Problem Description:

Volvo Bus Corporation (Volvo Bus) is recalling certain 2020 Volvo 9700 DOT vehicles. In the event of the alternator front bearing seizing, the alternator belt may continue to operate, causing the bearing to overheat.

Consequence:

An overheated alternator bearing can increase the risk of a fire.

Remedy:

Volvo Bus will replace the alternator belt, free of charge. Owner notification letters are expected to be mailed June 3, 2022. Owners may contact Volvo Bus customer service at 1-866-870-2046.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Volvo Bus Corporation's contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

