

Toyota Motor North America, Inc.

Vehicle Safety & Compliance  
Liaison Office  
6565 Headquarters Drive  
Plano, TX 75024

May 18, 2022

## **AMENDED DEFECT INFORMATION REPORT (22V238)**

This supplements Toyota's Part 573 Report of April 13, 2022 concerning the spot weld issue on certain Lexus NX vehicles.

Toyota previously reported the remedy for this condition was being developed. This amendment supplements the Part 573 Report to add the description of corrective repair action.

The revised Description of Corrective Repair Action is as noted below:

### Description of Corrective Repair Action:

All known owners of the subject vehicles will be notified to return their vehicles to a Lexus dealer. For all involved vehicles, Lexus dealers will inspect for the presence of spot-welds around the front shock absorber mounting areas. For vehicles with missing spot welds, additional welds will be added to the body panels. If the inspection determines that the body panels or any welds have failed, the body panels will be replaced.