

# ANA5 Stop Delivery/Recall Campaign - Inspection and rework of front seat wiring harnesses

---

## ANA5 Stop Delivery/Recall Campaign - Inspection and rework of front seat wiring harnesses

ID Number	ANA5
Models	Taycan (Y1A/Y1B/Y1C)
Model Years	2020-2022
Number of VINs affected	9,500
VIN list	Attached
Issue Description	In the affected vehicles, there is a possibility that the driver and passenger seat wiring harness could become damaged during longitudinal seat adjustment.
What should Dealers do?	<b>The repair is not available at this time. Please wait for further instructions. Please do not deliver affected vehicles in dealer inventory until further notice.</b>
What will Porsche do?	Vehicles affected by the Stop Delivery will be remedied prior to vehicle delivery. Customer vehicles will be brought into the dealer to have the remedy performed as soon as it is available.
TI Number	To be released at a later date.
Customer Reactive Statement	The safety of anyone travelling in one of our cars is our highest priority. For this reason, we regularly review the quality of our work. In the course of these reviews, it was discovered that in certain instances, a wiring harness under the front seats in some 2020 and 2021 Taycan vehicles may get caught as the seat is moved forward or back. If this happens, it could make the seat harder to move or inoperable. In rare cases, the wiring harness may be damaged and could affect the supplemental restraint system (air bags, se-

at belt pre-tensioners), causing the red air bag warning light to illuminate.

While no incidents have been reported, we will check the wiring harness in all recalled vehicles. Wiring harnesses that are undamaged will be affixed in place with additional material. Any that are damaged will be replaced.

Customers whose cars are affected will be contacted in due course for the work to be carried on a date convenient to them. There will be no charge for this work.

## Important information

**IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.**