Original Publication Date: April 28, 2022

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

SAFETY (NONCOMPLIANCE) RECALL 22TA04 (Remedy Notice)

Certain 2022 Model Year Tundra

Panoramic View Monitor System – Potential Failure to Display Rearview Image

Model / Years	Production Period	Approximate Total Vehicles	Approximate Stop Sale Dealer Inventory				
2022 Model Year	Mid-May 2021 – Mid April 2022	18,100	44				



On April 28, 2022, Toyota filed a Noncompliance Information Report (NCIR) with the National Highway Traffic Safety Administration (NHTSA) informing the agency of our intent to conduct a voluntary Safety (Noncompliance) Recall on 2022 model year Tundra vehicles.

Condition

In the affected vehicles, a software programming issue can cause individual cameras in the Panoramic View Monitoring (PVM) system, including the backup camera, to not display an image. If the backup camera image does not display when the vehicle is in reverse, the vehicle will not comply with safety regulations in certain markets and may increase the risk of a crash.

Remedy

Any authorized Toyota dealer will update the software in the Parking Assist ECU FREE OF CHARGE.

Covered Vehicles

There are approximately 18,100 vehicles covered by this Safety (Noncompliance) Recall. Approximately 233 vehicles involved in this Safety (Noncompliance) Recall were distributed to Puerto Rico.

Owner Letter Mailing Date

Toyota will notify owners by late June, 2022.

Toyota makes significant effort to obtain current customer name and address information from each state through industry resources when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Safety (Noncompliance) Recall announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.

Please note that only owners of the covered vehicles will be notified. If you are contacted by an owner who has not yet received a notification, please *verify eligibility by confirming through TIS prior to performing repairs*. Dealers should perform the repair as outlined in the Technical Instructions found on TIS.

Dealer Inventory Procedures

New Vehicles in Dealership Inventory

There are approximately 44 vehicles in new dealer inventory as of April 27, 2022.



Under Title 49, Section 30112 of the United States Code, a dealer cannot sell, offer for sale, or introduce or deliver for introduction in interstate commerce a new motor vehicle when it is aware that the vehicle does not comply with an applicable Federal Motor Vehicle Safety Standard or contains a defect related to motor vehicle safety. Further, 49 Code of Federal Regulations §577.13 requires us to provide the following advisory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

Toyota reimburses dealers for flooring costs associated with new vehicles held in dealership inventory until the recall remedy becomes available. Toyota provides these flooring reimbursements at 60-day intervals. Toyota reserves the right to withhold or charge-back any flooring reimbursement funds that may have been paid to the dealer if it determines that a new vehicle subject to a safety recall was sold without first being remedied.

Vehicle Safety Recall completion should always be verified through TIS. We request your assistance to ensure involved vehicles are identified and not delivered prior to performing the remedy.

NOTE:

- New vehicles in dealer inventory subject to a Safety Recall must be remedied before delivery into commerce under a sale or lease. Dealer-to-dealer trades as well as vehicle sales between dealers should not be made until a vehicle is remedied.
- Dealers can identify if any of their new and used inventory has any open campaigns in the Vehicle Inventory Summary available in Dealer Daily (Non SET and GST dealers: https://dealerdaily.toyota.com/). The Vehicle Inventory Summary may take up to 4 hours to populate information for newly launched campaigns.

Inspection Reminder Mirror Hang Tags for Covered Vehicles in New Dealer Stock

To easily recognize vehicles involved in this Safety (Noncompliance) Recall, each dealership should utilize Inspection Reminder Hang Tags. Inside the vehicle's glove box are stickers containing the VIN. Apply one of these stickers to the hang tag and install the hang tag in the vehicle. A sample copy of the Inspection Reminder Hang Tag has been included for your reference.



NOTE: Dealerships can order hang tags from the Material Distribution Center (MDC).

Part Number	Description	Quantity				
00411-140003	Inspection Mirror Hang Tag	25 Per Pack				

Pre-Owned Vehicles in Dealer Inventory

To ensure customer satisfaction, Toyota requests that dealers complete this Safety Recall on any used vehicles currently in dealer inventory that are covered by this Safety Recall prior to customer delivery. However, if the campaign cannot be completed (for example, due to remedy parts availability), delivery of a covered vehicle is acceptable if disclosed to the customer that the vehicle is involved in a Safety Recall.

Toyota expects dealers to use the attached Customer Contact and Vehicle Disclosure Form to obtain vehicle buyer information. Dealers are expected to provide a copy of the completed form, along with the most current FAQ, to the vehicle buyer. Toyota and the dealer may use this information to contact the customer when the remedy becomes available.

Keep the completed form on file at the dealership and send a copy to quality_compliance@toyota.com. In the subject line of the email state "Disclosure Form 22TA04" and include the VIN.

NOTE: Dealers can identify if any of their new and used inventory has any open campaigns in the Vehicle Inventory Summary available in Dealer Daily (**Non SET and GST dealers:** <u>https://dealerdaily.toyota.com/</u>). The Vehicle Inventory Summary may take up to 4 hours to populate information for newly launched campaigns.

Toyota Certified Used Vehicle (TCUV)

The TCUV policy prohibits the certification of any vehicle with an outstanding Safety Recall, Special Service Campaign, or Limited Service Campaign. Thus, no affected units are to be designated, sold, or delivered as a TCUV until all applicable Safety Recalls, Special Service Campaigns, and Limited Service Campaigns have been completed on that vehicle.

Toyota Rent-A-Car (TRAC) & Service Loaners

Toyota requests that dealers remove all TRAC and Service Loaner vehicles from service that are covered by a Safety Recall unless the defect has been remedied.

Customer Handling, Parts Ordering, and Remedy Procedures

Customer Contacts

Customers who receive the owner letter may contact your dealership with questions regarding the letter and/or the Safety (Noncompliance) Recall. Please welcome them to your dealership and answer any questions that they may have. A Q&A is provided to assure a consistent message is communicated.

If customers describe that they are experiencing the condition, advise them to turn the vehicle ignition off and back on again. Power cycling the ignition may allow the camera image to display.

Customers with additional questions or concerns are asked to please contact the Toyota Brand Engagement Center (1-888-270-9371) - Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.

Salvage Title Vehicles

Every attempt should be made to complete an open Safety Recall when circumstances permit, unless noted otherwise in the Safety Recall dealer letter.

For complete details on this policy, refer to Toyota Warranty Policy <u>4.17</u>, "What Is Not Covered by The Toyota New Vehicle Limited Warranty".

Media Contacts

It is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Aaron Fowles (469) 292-1097 in Toyota Corporate Communications. Please do not provide this number to customers. Please provide this contact only to media.

Parts Ordering Process - Non SET and GST Parts Ordering Process

It is possible that parts for this campaign are either required to be ordered in Campaign Part Order Request (CPOR) on Service Lane, or have been placed on Manual Allocation Control (MAC) due to potential limited part availability. Please check the CPOR/MAC report on Dealer Daily for the most up-to-date parts ordering information. Dealers can identify which parts ordering method to use by reviewing the parts information section of Dealer Daily and checking for a MAC code on the part numbers below. For MAC code C, order through CPOR. For MAC code D, refer to the MAC report for further instructions.

All Safety Recall, Service Campaign (SSC/LSC) parts are eligible for the Monthly Parts Return Program. Please refer to PANT Bulletin 2011-087 for campaign parts that are currently returnable under the Monthly Parts Return Program and for additional details.

Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently have completed all of the following courses:

• T623 Electrical Circuit Diagnosis

Always check which technicians can perform the repair by logging on to <u>https://www.uotdealerreports.com</u>. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

Remedy Procedures

Refer to TIS for Technical Instructions on repair. Conduct all non-completed Safety Recalls and Service Campaigns on the vehicle during the time of appointment.

Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

Parts Recovery Procedures

All parts replaced as part of this Safety Recall must be turned over to the parts department until appropriate disposition is determined. The parts department must retain these parts until notification via the Parts Recovery System (PRS) is received indicating whether to ship or scrap the parts. These parts are utilized by various departments for defect analysis, quality control analysis, product evaluation, as well as other purposes.


To help minimize dealer storage challenges, Toyota recommends that dealers:

- File the campaign claim accurately and promptly. The time a dealer is required to hold parts is based on when the campaign claim is paid by Toyota.
- Monitor the Warranty Parts Recovery Notifications and Part Scrap Report regularly.

Refer to Warranty Policies 9.3 and 9.6 for additional details

Warranty Reimbursement Procedures

Warranty Reimbursement Procedure



Op Code	Description	Flat Rate Hours				
22AH12	Reprogram Parking Assist ECU	0.7				

- The flat rate times include 0.1 hours for administrative cost per unit for the dealership.
- In the rare case that Parking Assist ECU contains the latest calibration ID (no software update needed), use opcode 22AH12.


Claim Filing Accuracy and Correction Requests

It is the dealer's responsibility to file claims correctly for this Safety (Noncompliance) Recall. This claim filing information is used by Toyota for various government reporting activities; therefore, claim filing accuracy is crucial. If it has been identified that a claim has been filed using an incorrect Op Code or a claim has been filed for an incorrect VIN, refer to Warranty Procedure Bulletin <u>PRO17-03</u> to correct the claim.

Customer Reimbursement

Reimbursement consideration instructions will be included in the owner letter.

Campaign Designation / Phase Decoder



Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Safety (Noncompliance) Recall.

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.



SAFETY (NONCOMPLIANCE) RECALL 22TA04 (Remedy Notice)

Certain 2022 Model Year Tundra

Panoramic View Monitor System – Potential Failure to Display Rearview Image

Frequently Asked Questions Original Publication Date: April 28, 2022

Q1: What is the condition?

A1: In the affected vehicles, a software programming issue can cause individual cameras in the Panoramic View Monitoring (PVM) system, including the backup camera, to not display an image. If the backup camera image does not display while the vehicle is in reverse, the vehicle will not comply with safety regulations in certain markets and may increase the risk of a crash.

Q1a: Are there any symptoms or warnings that the condition is present?

- A1a: Owners may notice one or more of the cameras in the Panoramic View Monitoring (PVM) system on the multimedia screen not displaying an image.
- **Q1b**: What should I do if I experience the condition?
- A1b Customers should turn the vehicle ignition off and back on again which may allow the camera image to display.

Q2: What is Toyota going to do?

A2: Toyota will send an owner notification by first class mail by late June 2022, advising owners to make an appointment with their authorized Toyota dealer to have the Parking Assist ECU software updated *FREE OF CHARGE*.

Q3: Which and how many vehicles are covered by this Safety (Noncompliance) Recall?

A3: There are approximately 18,100 vehicles covered by this Safety (Noncompliance) Recall.

Model Name	Model Year	Production Period						
Tundra	2022	Mid-May 2021 – Mid April 2022						

Q3a: Are there any other Lexus/Toyota/Scion vehicles covered by this Safety (Noncompliance) Recall in the U.S.?

A3a: No, there are no other Lexus/Toyota/Scion vehicles covered by this Safety (Noncompliance) Recall. This condition is specific to certain 2022 Model Year Tundra vehicles with Panoramic View Monitor, including those with the Multi-Terrain Monitor function.

Q4: How long will the repair take?

A4: The repair takes approximately 45 minutes. However, depending upon the dealer's work schedule, it may be necessary to make the vehicle available for a longer period of time.

Q5: What if I previously paid for repairs related to this Safety (Noncompliance) Recall?

A5: Reimbursement consideration instructions will be provided in the owner letter.

Q6: How does Toyota obtain my mailing information?

A6: Toyota uses an industry provider who works with each state's Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q7: What if I have additional questions or concerns?

A7: If you have additional questions or concerns, please contact the Toyota Brand Engagement Center at 1-888-270-9371 Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time. ΤΟΥΟΤΑ

Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive Plano, TX 75024 (469) 292-4000

CUSTOMER CONTACT & VEHICLE DISCLOSURE FORM

This form is not applicable for new vehicles in dealership inventory and TCUV units.

This vehicle is involved in a Safety Recall. At this time, <u>remedy parts are not available</u> and the remedy has **NOT** been performed. I understand that the vehicle will need to be returned to an authorized Toyota dealer to have the remedy performed at **NO CHARGE** when the remedy is available.

Customer Signature

Toyota recommends that you register with the Toyota Owners Community at <u>http://www.toyota.com/owners/</u> and regularly check recall applicability using <u>www.toyota.com/recall</u> or <u>www.safercar.gov</u>. You will need to input your 17-digit Vehicle Identification Number (VIN).

VIN																	Camp	baigr	Code	9			
Мос	del							Mo	odel	Yea	ar _						-						
Custor	ner Inf	ormatio	on																				
	Cust	omer N	lame											_	Custo	mer	Email	 					
	Custor	ner Ad	dress											_	Hom	e Ph	one #	! 					
														_	Mobil	e Ph	one #	: 					
														_			Date						
info	rmatio	vide thi n will o re, visit	nly be	e use	ed fa	or ca	тра	ign	con	าทน	ınic	atio	ons. I	f yo	u'd like	e to u	pdate	e you		-			

Dealer Information

Dealer Name/Address	Dealer Code	
_	Dealer Phone Number	
_	Dealer Staff Name	
_	Dealer Staff Signature	