

## CAMPAIGN LAUNCH STATUS

### N685 SAFETY RECALL- FRONT IMPACT SENSOR TORQUE CHECK



RECALL N685 - FRONT IMPACT SENSOR TORQUE CHECK	
AFFECTED MODELS	22MY New Range Rover (L460)
VOLUME AFFECTED	USA 19
REPAIR	Affected vehicles require a torque check on the two front impact sensor mounting bolts.
REPAIR TIME	0.1 hrs
CAMPAIGN LAUNCH	May 20 <sup>th</sup> , 2022
Notes	12 retailed units still require the repair. Retailers are requested to utilize mobile technicians to perform this simple torque check, thereby minimizing any inconvenience to customers.



PRINTED COPIES ARE UNCONTROLLED

## CAMPAIGN LAUNCH STATUS

### N685 SAFETY RECALL- FRONT IMPACT SENSOR TORQUE CHECK



#### Affected Retailed New Range Rover Vehicles

VIN	Dealer Code and Name	Current Vehicle Status Description
[REDACTED]	0652 Land Rover DFW	Retail Sale
[REDACTED]	0104 Land Rover Encino	Retail Sale
[REDACTED]	0114 Land Rover Buckhead	Retail Sale
[REDACTED]	0131 Land Rover North Dade	Retail Sale
[REDACTED]	0136 Land Rover Dallas	Retail Sale
[REDACTED]	0253 Land Rover South Dade	Retail Sale
[REDACTED]	0362 Land Rover Princeton	Retail Sale
[REDACTED]	0364 Land Rover Naperville	Retail Sale
[REDACTED]	0627 Land Rover Manhattan	Retail Sale
[REDACTED]	0649 Land Rover Schaumburg	Retail Sale
[REDACTED]	0666 Land Rover Santa Monica	Retail Sale
[REDACTED]	0686 Land Rover Pasadena	Retail Sale



PRINTED COPIES ARE UNCONTROLLED