

CAMPAIGN LAUNCH STATUS

N685 SAFETY RECALL- FRONT IMPACT SENSOR TORQUE CHECK



RECALL N685 - FRONT IMPACT SENSOR TORQUE CHECK	
AFFECTED MODELS	22MY New Range Rover (L460)
VOLUME AFFECTED	USA 19
REPAIR	Affected vehicles require a torque check on the two front impact sensor mounting bolts.
REPAIR TIME	0.1 hrs
CAMPAIGN LAUNCH	May 20 th , 2022
Notes	The 7 affected unsold vehicles are now closed. 11 retailed units still require the repair. Retailers are requested to utilize mobile technicians to perform this simple torque check, thereby minimizing any inconvenience to customers.



PRINTED COPIES ARE UNCONTROLLED