



R-2022-1
May, 2022

Recall:
Incorrect Front Brake Hose on RR-S
Models

Models Effected:
2022 350-500 RR-S 4-Stroke

Confidentiality Notice: This message (including attachments) contains information that may be confidential and is for authorized Beta Dealer's use only

Problem: A batch of 2022 RR-S 4-Strokes have come with the incorrect front brake hose installed.

Solution: Inspect units for the incorrect front brake hose, and if needed replace.



File a warranty request for the parts & labor listed below if needed.

Labor Code: B255

Labor Time: .5

Parts Needed:

29-09108-000 (Front Brake Hose)

4x 16-50510-000 (Crush Washer)