



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 9, 2022

Marie-Claude Simard
Bombardier Recreational Products, Inc.
726 St-Joseph Street
Valcourt, Quebec Canada JOE 2L0

NEF-107DM
22V-352

Subject: Defective Front Sprocket

Dear Marie-Claude Simard:

This letter serves to acknowledge Bombardier Recreational Products, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CAN-AM/SPYDER F3/2015-2019
CAN-AM/SPYDER RT/2015-2019

Mfr's Report Date: May 18, 2022

NHTSA Campaign Number: 22V-352

Components:

POWER TRAIN:MANUAL TRANSMISSION

Potential Number of Units Affected: 30,389

Problem Description:

Bombardier Recreational Products, Inc. (Bombardier) is recalling certain 2015-2019 Can-Am Spyder F3 and RT motorcycles. The front sprocket may be defective and prematurely wear, resulting in a loss of drive power.

Consequence:

A loss of drive power increases the risk of a crash.

Remedy:

Dealers will perform an interim repair until parts become available. Once parts are available, the front sprocket will be replaced, free of charge. Owner notification letters are expected to be mailed June 20, 2022. Owners may contact Bombardier customer service at 1-888-272-9222.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the front sprocket. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)). Please amend the Part 573 report to include the interim repair procedure.

AMENDED 573 REQUIRED.

We have received Bombardier's proposed owner notification letter and it is approved for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Bombardier Recreational Products, Inc.'s contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement