

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 9, 2022

Mr. Tony Sappington
Manager- Product Safety
Oshkosh Corporation
520 Hwy St E

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Alternator Cable Clamps Incorrectly Installed

Dear Mr. Sappington:

Dodge Center, MN 55927

This letter serves to acknowledge Oshkosh Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

OSHKOSH/S-SERIES/2019-2022

Mfr's Report Date: May 26, 2022

NHTSA Campaign Number: 22V-378

Components:

ELECTRICAL SYSTEM:ALTERNATOR/GENERATOR/REGULATOR

Potential Number of Units Affected: 1,316

Problem Description:

Oshkosh Corporation (Oshkosh) is recalling certain 2019-2022 S-Series 2.0 Concrete Mixers. Incorrectly installed alternator electrical cable clamps may rub against the vehicle frame or hydraulic hose, possibly damaging the alternator cables.

Consequence:

Damaged alternator electrical cables can increase the risk of a fire.

Remedy:

Oshkosh will provide instructions on how to inspect the wiring, reposition the clamps, and properly secure the cables. The repair can be performed by the owner or an Oshkosh service center, free of charge. Owner notification letters are expected to be mailed on June 17, 2022. Owners may contact Oshkosh's customer service at 1-888-686-7278.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Oshkosh Corporation's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

