

Part 573 Safety Recall Report

22V-390

Manufacturer Name : Dalton Enterprises, Inc.**Submission Date :** JUN 01, 2022**NHTSA Recall No. :** 22V-390**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Dalton Enterprises, Inc.

Address : 206 GIENOW ROAD

RURAL RETREAT VA 24368

Company phone : 999

Population :

Number of potentially involved : 6

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2022 Adam J2040

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : NHTSA recall 22E021 for Dometic CE99-ZF cooktops. Only purchased 6 units. 5 Units specific to this make and model. 1 Unit: Adam GS152 VIN end 6948

Production Dates : JUN 01, 2021 - MAR 31, 2022

VIN Range 1 : Begin : 5CLHG3521NR007260 End : TCLHG3521NR007261 Not sequentialVIN Range 2 : Begin : 5clhg1929mr007083 End : 5clhg1929mr007083 Not sequentialVIN Range 3 : Begin : 5clhg2122nr007302 End : 5clhg2112nr007302 Not sequentialVIN Range 4 : Begin : 5clhg222xnr007241 End : 5clhg222xnr007241 Not sequentialVIN Range 5 : Begin : 5clhg2520mr006948 End : 5clhg2520mr006948 Not sequential**Description of Defect :**

Description of the Defect : The burner control valve, mated directly to the control knob via the valve stem may leak gas. This gas will leak directly into the recessed portion of the cooktop, where the knobs and ignitor are located, and may be ignited by the active burner(s) resulting in a small pilot flame directly at the control knob

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The burner control valve, mated directly to the control knob via the valve stem may leak gas. This gas will leak directly into the recessed portion of the cooktop, where the knobs and ignitor are located, and may be ignited by the active burner(s) resulting in a small pilot flame directly at the control knob

Description of the Cause : The burner control valve, mated directly to the control knob via the valve stem may leak gas. This gas will leak directly into the recessed portion of the

cooktop, where the knobs and ignitor are located, and may be ignited by the active burner(s)

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR
Component Description : NR
Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Dometic Corporation
Address : 5155 Verdant Dr.
Elkhart Indiana 46516
Country : United States

Chronology :

Notifications from NHTSA and Dometic

Description of Remedy :

Description of Remedy Program : We have verbally contacted and emailed all but one unit owner that was in our facility. Dometic was given a list. Dometic is providing replacement units at N/C and allowing 1 hour labor reimbursement to service center. Owner's will receive service free of charge. Dometic requires a Recall Response Card to receive the replacement unit.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : All have been notified by phone and email. Upon seeing your notice below. Letter will go out 1st week of June

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : MAY 27, 2022 - JUN 03, 2022

* NR - Not Reported