

Part 573 Safety Recall Report

22V-433

Manufacturer Name : Cruiser RV**Submission Date :** JUN 17, 2022**NHTSA Recall No. :** 22V-433**Manufacturer Recall No. :** 99.03.21**Manufacturer Information :****Manufacturer Name :** Cruiser RV**Address :** 7805 North State Road 9
PO Box 130 Howe IN 46746**Company phone :** 866-277-5630**Population :****Number of potentially involved :** 2,985**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2022-2022 Cruiser Shadow Cruiser**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR**Descriptive Information :** The population was determined by cross-referencing out Production PO numbers with affected Flex-Tech shipments**Production Dates :** JUL 12, 2021 - APR 25, 2022**VIN Range 1 : Begin :** 5RXDB3225NN478370 **End :** 5RXDB3626N1510163 ☒ Not sequential**Vehicle 2 :** 2022-2022 Cruiser Embrace**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR**Descriptive Information :** The population was determined by cross-referencing our Production PO numbers with affected Flex-Tech shipments**Production Dates :** JUL 19, 2021 - MAR 15, 2022**VIN Range 1 : Begin :** 5RXNB3029N1480749 **End :** 5RXNB3623N1506690 ☒ Not sequential

Vehicle 3 : 2022-2022 Cruiser MPG

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The population was determined by cross-referencing our Production PO numbers with affected Flex-Tech shipments

Production Dates : JUL 20, 2021 - APR 28, 2022

VIN Range 1 : Begin : 5RXHB3026N1480768 End : 5RXHB3624N1511295 ☒ Not sequential

Vehicle 4 : 2022-2022 Cruiser Radiance

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The population was determined by cross-referencing our Production PO numbers with affected Flex-Tech shipments

Production Dates : JUL 16, 2021 - APR 11, 2022

VIN Range 1 : Begin : 5RXFB3026N1480728 End : 5RXFB3329N1509148 ☒ Not sequential

Vehicle 5 : 2022-2022 Cruiser Hitch

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The population was determined by cross-referencing our Production PO numbers with affected Flex-Tech shipments

Production Dates : AUG 09, 2021 - APR 20, 2022

VIN Range 1 : Begin : 5RXRB2117N1483022 End : 5RXRB2314N1510222 ☒ Not sequential

Vehicle 6 : 2022-2022 Cruiser Twilight

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The population was determined by cross-referencing our Production PO numbers with affected Flex-Tech shipments

Production Dates : JUL 12, 2021 - APR 28, 2022

VIN Range 1 : Begin : 5RXPB3529N1478789 End : 5RXPB332XN1512158 ☒ Not sequential

Vehicle 7 : 2022-2022 Cruiser Stryker

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The population was determined by cross-referencing out Production PO numbers with affected Flex-Tech shipments

Production Dates : JUL 28, 2021 - MAR 30, 2022

VIN Range 1 : Begin : 5RXGB3820N1480698 End : 5RXGB382XN1508426 ☒ Not sequential

Description of Defect :

Description of the Defect : Flex-Tech has informed us that the brass used in production may be porous causing small cracks in the LP Quick disconnect. Therefore the Quick disconnect/s in the LP gas system may be cracked.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A Crack in the LP disconnect can cause an LP leak. Excessive LP gas leak may lead to an explosion and fire, which may lead to property damage and personal injury.

Description of the Cause : Porous brass from the manufacturer can lead to cracks in the fitting when tightening during assembly.

Identification of Any Warning that can Occur : The owner may notice the smell of LP gas near the quick disconnect mounted under the trailer.

Involved Components :

Component Name 1 : LP quick disconnect

Component Description : LP quick disconnect female

Component Part Number : 76290W

Supplier Identification :

Component Manufacturer

Name : Enerco Group Inc.
Address : 4560 West 160 St.
c Ohio 44135
Country : United States

Chronology :

4/6/22 was notified by Thor Corp of Forest Rivers findings of faulty disconnects. 4/7 to 4/20 FRC and Warranty claims investigation and analysis. 4/19 Received shipment and PO information from Flex Tech. 4/20 received letter from Flex-Tech stating LP disconnect issue with Flex-Techs findings. 4/26 safety committee meeting voted for a voluntary recall. An investigation was called to determine the affected unit scope and range. Received final scope of units sold to Cruiser RV. 6/10 submitted amendment for recall 22v293. Informed Cruiser will have to submit a new recall.

Description of Remedy :

Description of Remedy Program : Cruiser will have an authorized dealer or repair center inspect the quick disconnect. If found faulty, the dealer will replace the LP quick connect and perform a test to verify proper installation. This repair should take no more than 20 minutes to complete. This defect will be corrected at no expense to you, the owner. All Reimbursements will be covered by Cruise's general reimbursement plan.

How Remedy Component Differs from Recalled Component : 76290W Quick Disconnect replacement will have the same part number 76290W

Identify How/When Recall Condition was Corrected in Production : On March 31, 2022 the supplier indicated that they had and were conducting immediate and complete internal retraining.

Recall Schedule :

Description of Recall Schedule : Cruiser will begin notifying owners/dealers once letters are approved

Planned Dealer Notification Date : JUL 17, 2022 - JUL 17, 2022

Planned Owner Notification Date : JUL 17, 2022 - JUL 17, 2022

* NR - Not Reported