



SAFETY RECALL

2020 through 2022 GL1800/B - ECU Update

BACKGROUND

Honda is launching a **SAFETY RECALL** on **CERTAIN 2020 through 2022 GL1800/B** vehicles to update the ECU for a potential defect that may result in engine stalling, increasing the risk of crash or injury.

AFFECTED UNITS

CERTAIN NEW or USED 2020 thru 2022 GL1800/B.

To search for applicable recall on a specific unit, you **MUST** use *Unit Information* on **iN** available June 21, 2022.

To manage your affected inventory, use your dealer *eResponsibility* Report on **iN** available June 22, 2022.

DEALER INVENTORY

As of June 21, 2022, **YOU MUST NOT SELL** any affected **NEW OR USED** motorcycle in the **AFFECTED UNIT** section until it is repaired, according to this Service Bulletin.

- To search for applicable recalls on a specific unit, you must use *Unit Information* on **iN**, available June 21, 2022.
- To manage your affected inventory, refer to *eResponsibility Report* on **iN**, available June 22, 2022.

PARTS INFORMATION

There are no parts necessary for this repair.

REPAIR PROCEDURE

The complete Service Bulletin with repair procedure, parts information, as well as warranty claim information is expected to be available on **iN** by the end of business Wednesday, June 29, 2022.

DEALER REPAIR RESPONSIBILITY

- Safety Recall repairs must be performed by a qualified technician.
- Installing the remedy parts exactly as shown in Repair Procedure instructions is critical for the recall remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this safety recall was properly performed.