RECALL 22V487 / 2022-371 REMEDY INSTRUCTIONS



Make(s): SEE BELOW Model(s): SEE BELOW Model Year(s): SEE BELOW

Concern:

SOME "RegO" BRAND SERVICE VALVES MAY NOT ALLOW A POL VALVE TO FULLY ENGAGE AND SEAT. THIS MAY ALLOW LPG LEAKAGE.

Repair Code: RC-026-01-00-004209

Allotted Time: .25 HRS.

Inspection Code: RC-026-05-00-004208

Allotted Time: 1.50 HRS.

Photo(s) Required: YES, OF FAILED VALVE

Prior Authorization Required: YES Part(s) Kit Number: SEE BELOW Part(s) Return: NO, DESTROY

Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN - 2017, 2020 & 2021 FREELANDER - FLC26RSC, FLC27QBC, FLC21RSC, FLC26DSC & FLC31MBF45

CERTAIN - 2019 - LEPRECHAUN - LPC280BHF

CERTAIN - 2020 - PURSUIT - PSA27XPSF

CERTAIN - 2021 - SPORTSCOACH - S1A365RB

CERTAIN - 2021 - ISATA - ISC24FWMCD, ISC24RWMCD, ISC28SSD, ISC28SSD4X4, ISC30FWD, ISC30FWD4X4,

ISC34DSD & ISC34DSD4X4

CERTAIN - 2022 - ISATA - ISC24FWMCD

CERTAIN - 2021 - 2022 - ISATA - ISC24FWM & ISC24RWM

PLEASE REVIEW AND FOLLOW THE ATTACHED DOCUMENTS FROM <u>REGO</u>. THESE DOCUMENTS WILL HELP YOU INSPECT AND, IF NECESSARY, REMEDY THE LPG TANK ON THE ABOVE LISTED VEHICLES.

PERFORM THE INSPECTION.

IF A LEAK AT THE DESCRIBED LOCATION (BY <u>REGO'S</u> DOCUMENTS) IS DETECTED TO BE PRESENT, ENSURE TO CAPTURE THE LEAK USING LEAK DETECTOR OR BY USING A SOAP SOLUTION. <u>PHOTOS OF THE BUBBLING SOLUTION(S) ARE REQUIRED</u>.

ONLY AN INSPECTION OR REMEDY MAY BE CLAIMED AGAINST A VIN, NOT BOTH CODES.

PLEASE FILE ALL CLAIMS THROUGH FOREST RIVER DEALER CONNECT AS NORMAL.

PART NUMBERS:

F100342390 22V487 MANCHESTER TANK RECALL SERVICE VALVE (901C3) F100342391 22V487 MANCHESTER TANK RECALL SERVICE VALVE (901C5)