

AUGUST 2022 Safety Recall 22V-508 (NHTSA) Campaign Bulletin CB22-J-002

IMPORTANT SAFETY RECALL

ENGINE EXHAUST BRAKE REPROGRAMMING – 22V-508

To: Isuzu Commercial Truck Service Managers and Parts Managers

This notice and Campaign Bulletin CB22-J-002 are being sent to inform you about Safety Recall -Engine Exhaust Brake Reprogramming in certain Isuzu commercial vehicles.

AFFECTED VEHICLES

2022MY Isuzu F-Series Vehicles (See affected 11 VINs below)

Model	Vehicle ID No.	Engine Serial Number

Model	Vehicle ID No.	Engine Serial Number

CONDITION

Isuzu Motors Limited has decided that a defect exists in certain 2022 model year Isuzu F-Series vehicles. Due to a software calibration error, the affected vehicles were built without engine exhaust braking functionality. Without engine braking, a driver may experience longer stopping distances than expected, increasing the risk of a crash.

CORRECTION

Isuzu dealers will have the Cummins Engine Control Module (ECM) reprogrammed with the correct calibration setting for the engine exhaust brake. This service will be performed free of charge.

OWNER NOTIFICATION

OWNER NOTIFICATION WILL BEGIN ON OR BEFORE SEPTEMBER 1, 2022.

Please ensure that all appropriate personnel within your dealership are aware of this Safety Recall – Engine Exhaust Brake Reprogramming.