

N720 H412 SAFETY RECALL – Autoliv Seat belt Retractor Functionality



SAFETY RECALL N720 H412 – Autoliv Seat belt Retractor Functionality

AFFECTED MODELS	22-23MY F-PACE, F-TYPE, and XF 22MY RR Sport 22-23MY RR Velar, Discovery Sport, Discovery, and Defender
VOLUME AFFECTED	H412 USA 176 H412 Canada 113 N720 USA 4,927 N720 Canada 645
REPAIR	The front seat belt pretensioner tube may have been damaged during the manufacturing process. Retailers will inspect the seat belt pretensioner tube and if damage is identified, following instructions in the bulletin, will replace any defective parts.
REPAIR TIME	Between 0.3 to 1.4 hrs + DIDO
CAMPAIGN LAUNCH	August 19 th , 2022
Notes	The recall repair bulletin has been published to TOPIx. There are 34 affected vehicles in dealer inventory that need to be rectified before sale. <1% of vehicles are expected to fail inspection and require a new part.