

H404 SAFETY RECALL – INCORRECT SPECIFICATION TAIL LAMPS



SAFETY RECALL H404 – INCORRECT SPECIFICATION TAIL LAMPS F-PACE

| | |
|-----------------|---|
| AFFECTED MODELS | 21-22MY F-PACE |
| VOLUME AFFECTED | USA 5326 Canada 699 |
| REPAIR | <p>The rear tail lamps may not be to specification. Retailers will inspect rear tail lamps and where an incorrect specification tail lamp has been installed, following instructions in the bulletin, will replace with correct parts.</p> <p>Less than 1% of vehicles are expected to need a replacement part</p> |
| REPAIR TIME | Inspect 0.1hrs Replacement lamps up to 0.4hrs for a pair + DIDO |
| CAMPAIGN LAUNCH | <p>Retailer Notification only was on August 4th, 2022. USA NAS22.08.001 and Canada NAS22.08.002. Repair bulletin target publication date is August 15th, 2022</p> |
| Notes | For sold cars, Customers will be notified by direct mail following the normal Recall process. |