N/	esla, Inc. ervice Bulletin	Replace Ankle Catcher Assembly			
SB-22-1					
July 25, 2022 Classification		Section/Group	Mobile Service	Configuration	
Recall Bulletin		10 - Body	Can Perform (where permitted)	All	
Model Year	Model	Country/Region	Build Location	Build Location	
2021 - 2022	Model S	United States	Fremont		

Recall Bulletins are mandatory service procedures that, unless they can be completed via a firmware update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Model S vehicles are equipped with a front bumper carrier structure (ankle catcher assembly) that may change the front passenger airbag deployment behavior, which may not meet regulatory requirements in certain low-speed crash scenarios.

Correction

Replace the ankle catcher assembly.

Correction Description		Correction	Time
Replace Ankle Catcher Assembly		S012210006	0.45

	Part Number	Description	Quantity
Parts Required	1649987-00-B	ANKLE CATCHER, MS	1

This part number was current at the time of publication. Use only the revision listed or later, unless otherwise specified in the Parts Catalog.

Shop Supplies Loctite 222 threadlocker

Procedure

Replace the ankle catcher assembly (refer to Service Manual procedure 10011202).