OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-532

Manufacturer Name: Daimler Trucks North America, LLC

Submission Date: JUL 22, 2022 NHTSA Recall No.: 22V-532 Manufacturer Recall No.: FL948



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 446 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2019-2023 Thomas Built Buses Minotour SRW

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: GAS

Descriptive Information: Certain Thomas Built Buses Minotour school buses with Single Rear Wheel ("SRW")

per wheel-end configuration of chassis may have an applied Vehicle Information Label and tire and Loading Information Label with incorrect tire size information

listed.

Production Dates: AUG 06, 2018 - MAY 04, 2022

Description of Noncompliance:

Description of the On the affected vehicles, the Vehicle Information Label and Tire and Loading

Noncompliance: Information Label with an incorrect tire size may not comply with 49 CFR

567.4 and 49 CFR 571.110.

FMVSS 1: 110 - Tire selection and rims

FMVSS 2: NR

Description of the Safety Risk: A noncompliance with 49 CFR 567.4 and 49 CFR 571.110 may lead to an

incorrect replacement tire being installed on the bus that is not sufficient for

the Rear GAWR and GVWR requirements increasing the risk of a crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Label

Component Description: Vehicle Information Label and Tire and Loading Information Label

Component Part Number: 206621 and 150479

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

On June 28 2022 DTNA received a report from a dealer of a potential discrepancy with the tire description on the Vehicle Information Label on four newly delivered buses. DTNA staff promptly began an investigation. DNTA staff reviewed build records to determine if any additional buses were built with the same discrepancy. DNTA also reviewed warranty records and field reports and found no similar issues. Once DTNA had sufficient information, on July 18 2022 DTNA decided to conduct a voluntary non-compliance recall on certain Thomas Built Buses Minotour SWR buses.

Description of Remedy:

Description of Remedy Program: A new label will be mailed to affected customers with the correct tire size

information. Repairs are expected to be performed by Daimler Trucks North America authorized service facilities. Details of the reimbursement

plan will be included in the owner's notification letter.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : SEP 15, 2022 - SEP 15, 2022 Planned Owner Notification Date : SEP 15, 2022 - SEP 15, 2022

Part 573 Safety Recall Report	22V-532	Page 3
*ND N + D + 1		
* NR - Not Reported		
The information contained in this report was submitted		