

# Part 573 Safety Recall Report

# 22V-568

**Manufacturer Name :** Tiffin Motorhomes, Inc.**Submission Date :** AUG 03, 2022**NHTSA Recall No. :** 22V-568**Manufacturer Recall No. :** TIF-125**Manufacturer Information :**

**Manufacturer Name :** Tiffin Motorhomes, Inc.  
**Address :** 105 2nd Street NW  
 PO Box 596 Red Bay AL 35582  
**Company phone :** 999

**Population :**

**Number of potentially involved :** 10  
**Estimated percentage with defect :** 100 %

**Vehicle Information :****Vehicle 1 :** 2022-2022 Tiffin Midas**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES**Body Style :** OTHER**Power Train :** GAS**Descriptive Information :** Center marker light left off on all units produced since the beginning of Midas production.**Production Dates :** DEC 21, 2021 - JUL 27, 2022**VIN Range 1 : Begin :** NR **End :** NR Not sequential**Description of Noncompliance :****Description of the Noncompliance :** Center marker light left off due to back-up camera was put in it's place in the rear cap.**FMVSS 1 :** 108 - Lamps, reflective devices, and assoc. Equipment**FMVSS 2 :** NR**Description of the Safety Risk :** It is a marker light used for others to see coach. If not there, the visibility of coach to others could be impaired.**Description of the Cause :** The hole in the rear cap that was supposed to house the center marker light was used instead for back-up camera. Error in production.**Identification of Any Warning that can Occur :** None.**Involved Components :**

Component Name 1 : Marker Light

Component Description : Center Marker Light

Component Part Number : 5127680 (Tiffin part #)

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

7/27/22 Safety Committee was advised of non-compliance due to center marker light had been left off. Decision was made to submit 573 for recall. No vote needed.

## Description of Remedy :

Description of Remedy Program : Tiffin will notify the affected population and have the camera moved down and center marker light inserted. This install will be at no charge to owner. If the owner has paid for any repairs related to this defect, they can submit their invoice to Tiffin Motorhomes for reimbursement.

How Remedy Component Differs from Recalled Component : The remedied unit will have the center marker light, whereas the recalled unit will not.

Identify How/When Recall Condition was Corrected in Production : Engineering Change Modification dated 7/28/2022 states "Move camera down and add center marker light".

## Recall Schedule :

Description of Recall Schedule : Owners and dealers will be notified of the recall and the Installation of the center marker light will be performed at no charge to the customer.

Planned Dealer Notification Date : SEP 30, 2022 - SEP 30, 2022

Planned Owner Notification Date : SEP 30, 2022 - SEP 30, 2022

\* NR - Not Reported