

## N725 H415 SAFETY RECALL - Audio Amplifier Module (AAM)



### SAFETY RECALL N725 H415 – Audio Amplifier Module (AAM)

AFFECTED MODELS	22MY Range Rover Velar 22MY F-PACE
VOLUME AFFECTED	H415 USA 26 H415 Canada 8 N725 USA 62 N725 Canada 2
REPAIR	A quantity of affected models have been shipped to retailers without audio amplifiers installed. Retailers should order and install the necessary amplifier as per the service bulletin.
REPAIR TIME	Between 0.7 to 0.9 hrs + DIDO
CAMPAIGN LAUNCH	August 18 <sup>th</sup> , 2022
Notes	Any vehicle already repaired under a shortage claim has been forced closed in the recalls.