



March, 2023

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **22S54 - Rear View Camera Inoperable (Missing Audio Control Module)**
and Description:

What is the issue? On your vehicle, it may be possible that the vehicle was manufactured with a missing Audio Control Module (ACM). The ACM supports various functions including rearview camera display, radio functionality, center stack display, center stack button functionality, USB functionality and others. A missing ACM will result in no rear-view camera display for vehicles equipped with a rear-view camera.

When the vehicle is placed into reverse gear, the rear-view camera image will not display on screen, increasing the risk of a crash and/or injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2023

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S54 - Cámara trasera no funciona (módulo de control de audio faltante)**

¿Cuál es el problema? Es posible que su vehículo haya sido fabricado sin módulo de control de audio (ACM). El ACM admite diversas funciones, incluida la visualización de la cámara trasera, la funcionalidad de la radio, la pantalla de la consola central, la funcionalidad del botón de la consola central, la funcionalidad de USB entre otras. La ausencia del ACM se traducirá en que no se pueda visualizar la cámara trasera en vehículos equipados con cámara trasera.

Quando el vehículo se coloca en el engrane de reversa, la imagen de la cámara trasera no aparecerá en la pantalla, lo que aumenta el riesgo de choque o de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0483933 A / 000000000000206 / 206



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶