# **Vermeer MV Solutions, Inc.**

Trenchless Piedmont, SC 29673 USA

FIELD CAMPAIGN SERVICE BULLETIN #: SMV2022-015 DATE: 13 October 2022

CAMPAIGN Mandato
TYPE: DEALER

Mandatory – Product Safety DEALER INSTALLATION ONLY

CAMPAIGN CATEGORY:

Kit and Bulletin

MACHINE/	SERIAL		
ATTACHMENT MODEL(S):	Included	Excluded	Kit version
AIR533SDT			
AIR535SDT			VMV01
AIR555SDT			
AIR573SDT	See attached listing on		
AIR833SDT	page 4 of this bulletin for specific serial/unit	None	
AIR835SDT	numbers		
AIR855SDT			
AIR873SDT			
AIRSDT			

Subject:



Trailer Frame Reinforcement Kit (VMV000028)

# Background:

Vermeer MV Solutions, Inc. has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2011 – 2020 Vac-Tron AIR533SDT, AIR535SDT, AIR555SDT, AIR573SDT, AIR833SDT, AIR835SDT, AIR855SDT, AIR873SDT, and AIRSDT vacuum excavator trailers. Vermeer Corporation is administering this product safety campaign on behalf of Vermeer MV Solutions, Inc.

# TRAILER FRAME FAILURE MAY OCCUR

Frame bending or distortion can develop in the trailer main frame which can result in loss of stability while towing.

# DEATH OR SERIOUS INJURY POSSIBLE

When towing the vacuum excavator trailer on public roadways, **death or serious injury** may result due to the loss of control of the vacuum excavator trailer and towing vehicle. A frame failure may increase the risk of a crash. Property or equipment damage may also occur.

# Solution:

#### IMMEDIATE MACHINE MODIFICATIONS REQUIRED

VMV000028 has been created to provide the necessary parts and instructions to add a plate gusset to reinforce the trailer frame. **The kit must be installed as soon as possible.** 

Please be reminded that it is a violation of federal law for you to sell or lease the machines covered by this notification until this recall has been performed on these machines. Substantial civil penalties apply to violations of this law.

Vermeer Corporation is administering this product safety alert on behalf of Vermeer MV Solutions, Inc.

# DEALER PARTICIPATION REVIEW REPORT, ORDER KITS, CONTACT CUSTOMERS

 Reports will be emailed during the week of October 13, 2022, to dealerships shown in our records which have units in their territory affected by this recall. Please review the report for accuracy, including owner and/or address changes.

If the information contained in the report is **not** correct, please notify the product safety department on or before October 26, 2022, at:

Telephone: 641-621-7060 Fax: 641-621-8562

Email: productsafetv@vermeer.com

- 2. **Dealership orders kits** by calling 888-822-8766 (Florida). Each dealership should determine the quantity of kits to order initially depending upon the number of units that may be available for immediate upgrade. **Do not order more kits than needed for immediate installation.**
- 3. Contact your affected customer(s) to schedule a mutually acceptable time to upgrade their machine(s). *Note*: Letters will be sent to the customer(s) on or about October 27, 2022. *Also refer to Owner Notification section below*.

If you have any questions concerning the installation of VMV000028, please contact Vermeer MV Solutions service department at 888-822-8766 (Florida).

#### REIMBURSEMENT

Upon completion of each kit installation, a campaign warranty claim must be submitted to the warranty department for reimbursement of the cost of parts and labor to install the kit. Labor hours to install: 1.5 hours.

Travel will be paid up to \$200 (\$1 per mile with a \$200 max round trip) with copy of work order attached for retailed machines not in dealer inventory. If dealer

repairs more than one machine at same location on one trip, travel will only be paid on one of the model/VINs. The dealer may not charge the customer for travel for this campaign per NHTSA, contact service if you have any questions.

**Note**: Future notices to dealers and owners are dependent upon the receipt of warranty claims.

# **OWNER NOTIFICATION**

**Sample letter:** Included at the end of this bulletin is a sample letter which will be sent by Vermeer Corporation on behalf of Vermeer MV Solutions directly to the owners on or about October 27, 2022, via USPS certified/registered mail. Owner registrations indicate no translations are required for this campaign. The owner letter will only be available in English.

This owner notification/letter instructs the owner **to contact their local dealership** to arrange for a time to have the kit installed. After receiving VMV000028 from Vermeer MV Solutions, you must **contact your affected customer(s) immediately** and schedule a mutually acceptable time to upgrade their machine(s).

We regret any inconvenience these corrective measures may cause you. This required work is for the safety of the towing vehicle occupants and other drivers and passengers on the public roadways.

Reimbursement:

M Product Safety ∆lert

# **VERMEER MV SOLUTIONS, INC.**

Attachment: VMV000028 Kit Instructions

Product Safety Alert: Install immediately

Completion schedule:

<ul> <li>□ 90 days from MM/DD/YYYY</li> <li>□ 180 days from MM/DD/YYYY</li> <li>□ 1 year from MM/DD/YYYY</li> <li>□ Only units within standard limited warranty period</li> <li>□ N/A</li> </ul>				☐ Product Compliance ☐ All units listed above with less than hours or warranty start date in the last months ☐ Parts ☐ Labor paid (Labor code: SB22) ☐ Only units within standard limited warranty period ☐ No reimbursement				
Internal reference:			Not applicable			12	Exterior lighting	
TREAD Act Code		02	Suspension	$\boxtimes$	16	Structure		
(Choose one or		03	Service brake system, hydraulic			17	Latch	
more applicable		04	Service brake system		19	Tires		
codes)		05	Parking brake		20	Wheels		
		11	Electrical			21	Trailer hitch	

AFFECTED MACHINES - VMV010028								
Model	VIN	SERIAL/ UNIT		Model	VIN	SERIAL/ UNIT		
AIR533SDT	REDACTED	141169		AIR855SDT	REDACTED	109937		
AIR533SDT		141196		AIR855SDT		110232		
AIR533SDT		141331		AIR855SDT		110231		
AIR535SDT		141295		AIR855SDT		111318		
AIR535SDT		131399		AIR855SDT		111319		
AIR555SDT		121166		AIR855SDT		109978		
AIR555SDT		111119		AIR855SDT		109980		
AIR555SDT		111135		AIR855SDT		111381		
AIR555SDT		111467		AIR873SDT		171140		
AIR555SDT		111244		AIR873SDT		181166		
AIR555SDT		121356		AIR873SDT		171256		
AIR573SDT		161350		AIR873SDT		171304		
AIR833SDT		141170		AIR873SDT		161266		
AIR833SDT		151128		AIR873SDT		181551		
AIR833SDT		141198		AIRSDT		191114		
AIR833SDT		141199		AIRSDT		191115		
AIR833SDT		141226		AIRSDT		191421		
AIR835SDT		131306		AIRSDT		191275		
AIR855SDT		109991		AIRSDT		191030		
AIR855SDT		131024		AIRSDT		191479		
AIR855SDT		121262		AIRSDT		200066		
AIR855SDT		121283		AIRSDT		200427		
AIR855SDT		110208						



NHTSA SAFETY RECALL NUMBER 22V-664

**Product Safety Department** 

productsafety@vermeer.com

Vermeer Corporation

1210 Vermeer Rd East Pella. Iowa 50219 USA

IMPORTANT SAFETY RECALL

SAMPLE OWNER LETTER **First Notice** 

Trailer Frame Reinforcement Kit (VMV000028)

Model: «Model»

This notice applies to your vehicle,

Serial No: «VIN»

October 13, 2022

Dear «MODEL» owner:

This notice is sent to you in accordance with the requirements of the U.S. National Traffic and Motor Vehicle Safety Act.

Vermeer MV Solutions, Inc. has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2011 – 2020 Vac-Tron AIR533SDT, AIR535SDT, AIR555SDT, AIR573SDT, AIR833SDT, AIR833SDT, AIR835SDT, AIR873SDT and AIRSDT vacuum excavator trailers. Vermeer Corporation is administering this product safety campaign on behalf of Vermeer MV Solutions, Inc. According to our records, you currently own a Vac-Tron «MODEL» vacuum excavator trailers. The model and serial number are shown at the top center of this letter.

# TRAILER FRAME FAILURE MAY OCCUR

Frame bending or distortion can develop in the trailer main frame which can result in loss of stability while towing.

#### **DEATH OR SERIOUS INJURY POSSIBLE**

When towing the vacuum excavator trailer on public roadways, **death or serious injury** may result due to the loss of control of the vacuum excavator trailer and towing vehicle. A frame failure may increase the risk of a crash. Property or equipment damage may also occur.

# IMMEDIATE MACHINE MODIFICATIONS REQUIRED

VMV000028 has been created to provide the necessary parts and instructions to add a plate gusset to reinforce the trailer frame. **This kit must be installed as soon as possible**. Vermeer Corporation is administering this product safety alert on behalf of Vermeer MV Solutions, Inc.

Please contact your authorized independent Vermeer dealer immediately to arrange a mutually acceptable time and location to install VMV000028 at no cost to you for labor or materials. The installation of this kit is estimated at 1.5 hours of labor. You must have your machine upgraded for these safety features.

Contact your local Vermeer dealer: «Service Dealer Name»

«Serv Dealer Add1» «Serv Dealer Add2»

«Serv\_Dealer\_City» «Serv\_Dealer\_St» «Serv\_Dealer\_Zip»

«SERV\_DEALER\_COUNTRY»

Telephone: «Serv Dealer Phone»

If you no longer own this unit, please notify the product safety department at:

Toll-free: 800-829-0051, option 1

Telephone: 641-621-7060

Email: productsafety@vermeer.com

If possible, please provide the name and address of the new owner.

We regret any inconvenience that these corrective measures may cause you. The required work is for the safety of the of the towing vehicle occupants and other drivers and passengers on the public roadways.

# Regards,

# PRODUCT SAFETY DEPARTMENT

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If the authorized dealer has failed or is unable to remedy the defect without charge and within a reasonable time, contact Vermeer product safety by email at productsafety@vermeer.com or by calling 800-829-0051 or 641-621-7060. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590; or call the Vehicle Safety Hotline at 888-327-4236 (TTY: 1-800-424-9153); or go to <a href="https://www.safercar.gov">https://www.safercar.gov</a>