



March, 2023

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2022 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **22C23 - Improper Passenger Air Bag Deployment - RH Topper Substrate Delamination and Description:**

What is the issue? The passenger side instrument panel cover on your vehicle, which is located on the dashboard and houses the airbag, may interfere with the intended passenger airbag cushion opening and alter that airbag's inflation characteristics.

A malfunctioning passenger side instrument panel cover may prevent the airbag from properly deploying, which could increase the risk of injury to the front passenger occupant in a crash. The passenger side instrument panel cover on these vehicles may also fragment during airbag deployment and project fragments toward the occupant, increasing the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2023

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2022 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22C23 - Despliegue incorrecto de la bolsa de aire del pasajero - Delaminación de sustrato superior derecho**

¿Cuál es el problema? La cubierta del panel de instrumentos del lado del pasajero de su vehículo, la cual se ubica en el tablero y aloja la bolsa de aire, podría interferir con la apertura del cojín de la bolsa de aire del pasajero previsto y alterar las características de inflado de dicha bolsa de aire.

Si una cubierta del panel del instrumentos del lado del pasajero presenta un mal funcionamiento, la bolsa de aire podría no desplegarse correctamente, lo cual podría aumentar el riesgo de lesiones al pasajero delantero en un choque. La cubierta del panel de instrumentos del lado del pasajero en estos vehículos también se podría fragmentar durante el despliegue de la bolsa de aire y proyectar fragmentos hacia el ocupante, lo cual aumenta el riesgo de sufrir lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0035740 A / 000000000000001 / 1



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

