

Part 573 Safety Recall Report

22V-754

Manufacturer Name : Shyft Group**Submission Date :** OCT 07, 2022**NHTSA Recall No. :** 22V-754**Manufacturer Recall No. :** 22-11**Manufacturer Information :**

Manufacturer Name : Shyft Group

Address : 1541 Reynolds Road
Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 451

Estimated percentage with defect : 14 %

Vehicle Information :

Vehicle 1 : 2022-2022 Utilimaster Walk-In Vans

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The basis of this recall is limited to a specific production run under a specific customer specification.

Production Dates : JAN 04, 2022 - OCT 04, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The transmission shifter cable may rest against the engine's exhaust manifold.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The transmission shifter cable outer coating may melt and allow the allow chafing of the main cable. This could increase the risk of a fire or the inability to shift the transmission which could increase the risk of a crash.

Description of the Cause : Pending

Identification of Any Warning that can Occur : Melting of the transmission shifter cable coating could occur without warning.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Pending

Description of Remedy :

Description of Remedy Program : For vehicles subject to this recall, they will be inspected to ensure the transmission shifter cable is secured away from the exhaust manifold. All vehicles subject to this recall are within their respective warranty period and any failures would have been covered under the vehicle's warranty.

How Remedy Component Differs from Recalled Component : The remedied vehicles will have the transmission shifter cable secured away from the exhaust manifold by way of clamps.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : SHYFT DOES NOT HAVE DEALERS FOR THIS PRODUCT AND THEREFORE NO DEALER NOTICE WILL BE ISSUED.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : OCT 28, 2022 - OCT 28, 2022

* NR - Not Reported