

REPAIR INSTRUCTIONS
KZ RECALL
NHTSA 22V-756
Transport Canada 2022-585
Internal KZ-2022-05

Vehicles subject to this recall may have been manufactured without an egress (EXIT) window in the Roadside living room slide out. Standards require one (1) egress window in this location. For floorplans with two (2) windows in the slide out, only one (1) is required to be an egress window.

Inspection

Inspect roadside slide out for egress window located in slide room. If egress window is present, file claim for inspection only. No further action necessary. If no egress window is present, proceed to REPAIR.

Repair

One egress window must be installed in the roadside slide out. If the floorplan only has one window in the slide out, replace with an egress window (part number below). If the roadside slide out has two windows, one must be replaced with an egress window.

Flat rate : Inspection .3
Repair 1.0

Code: 2301-22V-756

Part number: 161229