



Stacy L. Balzer
Operating Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 21, 2022

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice -
Safety Recall 22S66**
Certain 2022 Model Year Bronco Sport Vehicles
Fuel Tank Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Bronco Sport	2022	Hermosillo	August 10, 2022 through August 11, 2022

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In all of the affected vehicles, the Fuel Pump Control Module (FPCM) bracket that secures the module to the fuel tank may become detached. If the FPCM bracket is not secured to the fuel tank, pulling stress is applied to the FPCM wiring harness connector, and over time pulling stress of the FPCM connector may lead to a loss of the electrical connection resulting in a non-functional FPCM. Alternatively, the FPCM may become damaged due to continued impacts against the body of the vehicle and the fuel tank, resulting in a non-functional FPCM. When driving on a bumpy road, the customer may experience a clunk type noise from under the rear seat of the vehicle. A non-functional FPCM prevents fuel from being supplied to the engine, potentially resulting the Malfunction Indicator Light (MIL) to illuminate and a sudden loss of motive power to the vehicle, increasing the risk of crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers the week of November 28, 2022 when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

ATTACHMENTS

Attachment I: Affected Vehicles VIN List

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink that reads "Stacy L. Balzer". The signature is written in a cursive, flowing style.

Stacy L. Balzer

**NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice -
Safety Recall 22S66
Certain 2022 Model Year Bronco Sport Vehicles
Fuel Tank Replacement**

AFFECTED VEHICLES VIN LIST

The following table contains a list of affected vehicles.

AFFECTED VIN NUMBERS

3FMCR9A63NRD84708	3FMCR9B69NRD82945
3FMCR9A64NRD89934	3FMCR9B69NRD89331
3FMCR9B60NRD83269	3FMCR9B6XNRD90200
3FMCR9B60NRD89296	3FMCR9B6XNRD90472
3FMCR9B60NRD90741	3FMCR9B6XNRD94974
3FMCR9B62NRD83550	3FMCR9C61NRD90259
3FMCR9B64NRD91522	3FMCR9C63NRD94006
3FMCR9B65NRD83574	3FMCR9C66NRD88488
3FMCR9B65NRD84370	3FMCR9C68NRD94860
3FMCR9B66NRD90145	3FMCR9C6XNRD66574
3FMCR9B67NRD91790	3FMCR9D97NRD89402
3FMCR9B68NRD83889	3FMCR9D98NRD81213
3FMCR9B68NRD91118	3FMCR9D99NRD91541
3FMCR9B68NRD94228	