

ANB6 Recall campaign - Checking screw connection for belt end attachment left and right and replace seat frame if necessary

ANB6 Recall campaign - Checking screw connection for belt end attachment left and right and replace seat frame if necessary

ID Number	ANB6
Models	911 GT3 / GT3 Touring (992)
Model Years	2022
Number of VINs affected	15
VIN list	Attached
Issue Description	Due to an assembly process deviation that has since been corrected, on some of the potentially affected vehicles equipped with optional Full Bucket Seats, the screw attaching the lower seatbelt anchor to the seat frame may not have been tightened to the specification.
What Should Dealers Do?	The repair is not available at this time.
What will Porsche Do?	Vehicles will have the remedy performed once it is available.
TI Number	TI to be released at a later date
Customer letter	To be posted at a later date
Customer Reactive Statement	The safety of anyone travelling in one of our cars is our highest priority. For this reason, we regularly review the quality of our work. In the course of these reviews, it was discovered that in certain model year 2022 911 GT3 cars, one of the screws anchoring the seatbelt harness to the seat frame may not have been tightened to meet the specifications. Only fifteen cars with the optional Full Bucket Seats are potentially affected. No incidents have been reported. Customers will be promptly notified so that Porsche dealers can quickly inspect the affected vehicles. There will be no charge for this.

ANB6 Recall campaign - Checking screw connection for belt end attachment left and right and replace seat frame if necessary