

# Part 573 Safety Recall Report

# 22V-805

**Manufacturer Name :** Sunset Park & RV Inc.

**Submission Date :** OCT 26, 2022

**NHTSA Recall No. :** 22V-805

**Manufacturer Recall No. :** 22E-055



## Manufacturer Information :

**Manufacturer Name :** Sunset Park & RV Inc.

**Address :** 1055 N 625 W

Shipshewana IN 46565

**Company phone :** 574-238-9081

## Population :

**Number of potentially involved :** 867

**Estimated percentage with defect :** 5 %

## Vehicle Information :

**Vehicle 1 :** 2022-2022 Sunset Paark & RV Sun Lite & Rush

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The electric awning has a welded seam on the fabric that may separate, potentially allowing the awning to drop below normal operation.

**Production Dates :** FEB 01, 2022 -JUL 31, 2022

**VIN Range 1 : Begin :** 7J3U1EE17NS005037 **End :** 7J3U1EE1XNS007901  Not sequential

## Description of Defect :

**Description of the Defect :** Lippert Electric Awning 18' or Less

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** The welded seam may separate allowing the awning to drop.

**Description of the Cause :** Insufficient Weld Penetration

**Identification of Any Warning** NR  
that can Occur :

## Involved Components :

Component Name 1 : Electric Retractable Awning

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : Lippert

Address : PO Box 2888

Elkhart Indiana 46515

Country : United States

## Chronology :

Sunset Park was notified by Lippert through an email about the recall.

## Description of Remedy :

Description of Remedy Program : Remedy program will include providing instructions for inspection and repair or replacement as needed of awnings which do not pass the inspection or have an occurrence. If repair or replacement is needed Lippert will supply the necessary items to complete the repair or replace the faulty product. Lippert will reimburse all OEM's, dealers, mobile repair companies and/or consumers for all costs associated with inspection, repair and/or replacement of the affected awnings.

How Remedy Component Differs from Recalled Component : Replacement material has been produced after 06.20.2022 and has been certified through validated improved processes.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production on 6/16/2022 by implementing and utilizing new processes. The new processes were determined after also reviewing machine parameters and identifying and removing potential areas for weld inconsistencies. Quality checks have been increased in frequency and periodic destructive tests implemented.

## Recall Schedule :

Description of Recall Schedule : As an OEM, we will notify all the dealers we have sold the

involved product to. We will assist the dealers as needed in their notification to consumers. The dates I am entering will be for our dealer notification.

Planned Dealer Notification Date : NOV 01, 2022 - NOV 16, 2022

Planned Owner Notification Date : NOV 17, 2022 - DEC 01, 2022

\* NR - Not Reported