TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER			
				Country	Beginning Model Year	Ending Model Year	Vehicle
				USA	2022	2022	ATLAS
Safety Recall 42M2	Safety Recall	42M2	What vehicles are included in Safety Recall 42M2?	USA	2022	2023	ATLAS CROSS SPORT
421012	recuii	721012	What is the safety concern for Safety Recall 42M2?	The proper tightening procedure at the supplier may not have been performed on the bolts on the driver side (left side) rear trailing arm. The bolts may loosen over time and fall out, or the trailing arm may fracture due to overload around the remaining bolt(s). This could cause excessive movement of the driver side (left side) rear wheel bearing carrier, which can lead to a change in vehicle handling characteristics. If this were to occur there could be a sudden loss of vehicle control. This may increase the risk of a crash. If the affected bolts loosen, the customer may notice an unusual (knocking) noise from the rear suspension and possibly a change in the vehicle handling. Should this occur, owners are advised to contact an authorized Volkswagen dealer without delay to have the vehicle inspected/repaired.			
			Are there any precautions I should take because my vehicle is part of Safety Recall 42M2?				
			What is the repair for the Safety Recall 42M2?	autho replac rear tr	rized Vo e the drailing ar	lkswagei iver side m bolts.	ial issue, your n dealer will (left side)
			When will the repair for Safety Recall 42M2 be available?	Please Volksv sched an ap	e contac wagen c ule this pointme	ct your au lealer wit recall rep	nave begun. uthorized hout delay to pair. To set up please visit ealer.