

December 14, 2022

Ms. Pascale Belanger Volvo Bus Corporation 260 Banker road Plattsburgh, NY 12901

Subject: Incorrectly Installed GPS Devices

Dear Ms. Belanger:

This letter serves to acknowledge Volvo Bus Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

VOLVO BUS/9700/2022

Mfr's Report Date: December 12, 2022

NHTSA Campaign Number: 22V-917

### **Components:**

EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM) VEHICLE SPEED CONTROL:ACCELERATOR PEDAL

# Potential Number of Units Affected: 20

### **Problem Description:**

Volvo Bus Corporation (Volvo Bus) is recalling certain 2022 9700 buses. The GPS devices may have been installed incorrectly, which can cause an accelerator pedal sensor malfunction and lead to an unexpected loss of drive power.

### **Consequence:**

A loss of drive power can increase the risk of a crash. Additionally, a disabled bus may require an evacuation procedure in an uncontrolled traffic situation, increasing the risk of injury to passengers.

### **Remedy:**

Prevost will inspect and reinstall the GPS devices, if necessary, free of charge. Owner notification letters are expected to be mailed January 31, 2023. Owners may contact Volvo Bus' customer service at 1-866-870-2046.

### Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107DR 22V-917

# Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

### AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Volvo Bus Corporation's contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely,

Alae Andry

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

