

# 22PBF - 579 MLU Molded Hood Mirror Safety Recall

[Edit](#) [Clone](#)

## Number

22PBF

## Supplier

Velvac

## Description

579 MLU Molded Hood Mirror Safety Recall

## Date

3/13/2023

## What's New

Safety Recall - A mirror with a pivot joint break that does not have a wire harness or tether can result in foreign object debris on the roadway increasing the risk of a crash and/or injury.

## Introduction

Certain model 579 MLU trucks equipped with molded hood mirrors may experience a mirror pivot-joint failure. Within that population of trucks, there are mirrors that do not have a wire harness or tether to keep the upper half of the mirror with the truck if the pivot joint fails.

## Situation

2,995 (2,565 US and 430 CAN) model 579 MLU MY 2022-2023 with molded hood mirror.

## Resolution

### Campaign

Inspect mirrors for presence of wire harness or tether. Replace mirror assembly if no wire harness or tether is present.

## Federal Law

---

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

## Warranty

---

### PETERBILT WARRANTY STATEMENT

There is no time or mileage limit for this recall. Peterbilt will pay for parts at dealer net plus applicable mark up and labor. All vehicles within this recall will need to have the hood mirrors inspected for the presence of a wire harness or tether. If neither is present, the mirror must be replaced.



#### NOTE

If a truck arrives at the dealer to have repairs related to 22PBF performed and it has a mirror with a broken pivot joint that is equipped with a wire harness or tether: ***This bulletin does not apply, and repair will need to be processed through standard warranty.***



#### NOTE

A picture of the serial number for the mirror being replaced must be attached to the warranty claim or the claim may be denied.

**Take-Off Parts Disposition:** Destroy take-off parts 30 days after claim is paid

PRWS CLAIM CODING			
<b>Campaign Code:</b>	22PBF	<b>Campaign Type:</b>	Safety Recall
<b>Claim Category:</b>	Truck	<b>Repair Type:</b>	Proactive
<b>Customer Concern Code:</b>	62	<b>Causal Code:</b>	23
<b>Corrective Action Code:</b>	12	<b>Responsibility Code:</b>	SUPPLIER
<b>Failure Location:</b>	002-010-006	<b>Causal Part:</b>	<p><b>L59-6006-100</b> (Black Mirror Housing)</p> <p><b>L59-6006-100R</b> (Black Mirror Housing)</p> <p><b>L59-6006-200</b> (Chrome Mirror Housing)</p> <p><b>L59-6006-200R</b> (Chrome Mirror Housing)</p>
<b>Supplier Code:</b>	18331AA	<b>SRT Code:</b>	<p><b>B22-PFA (0.1 hrs.)</b> Inspection only of the hood mirrors per bulletin procedure.</p> <p><b>B22-PFB (0.3 hrs.)</b> Inspection and Replacement of both hood-mounted mirrors (Black Mirror Housings).</p> <p><b>B22-PFC (0.2 hrs.)</b> Inspection and Replacement of one hood-mounted mirror –</p>

			<p>Left Hand Side (Black Mirror Housing). <b>B22-PFD (0.2 hrs.)</b> Inspection and Replacement of one hood-mounted mirror – Right Hand Side (Black Mirror Housing). <b>B22-PFE (0.3 hrs.)</b> Inspection and Replacement of both hood-mounted mirrors (Chrome Mirror Housings). <b>B22-PFF (0.2 hrs.)</b> Inspection and Replacement of one hood-mounted mirror – Left Hand Side (Chrome Mirror Housing). <b>B22-PFG (0.2 hrs.)</b> Inspection and Replacement of one hood-mounted mirror – Right Hand Side (Chrome Mirror Housing).</p>
--	--	--	--

## Procedure

**Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.**

Please see repair procedure in the Links section of this bulletin.

**NOTE**

**A picture of the serial number for the mirror being replaced must be attached to the warranty claim or the claim may be denied.**

## Parts

---

**Parts are available from PACCAR Parts.**

**Prior to ordering parts, please verify if there is an existing backorder in your system. Existing backorders will be fulfilled. Please be sure that backorders are allocated to support this campaign.**

**PACCAR Parts is actively working with the supplier to increase inventory levels to meet demand related to this bulletin.**

**Due to demand, PACCAR Parts is currently limiting dealer orders for all mirror part numbers involved in this campaign to one of each, per**

**dealer per day.**

Quantity	Part Number	Description
1	L59-6006-100	HOOD MIRROR, LH, BLACK, NON-HEATED
1	L59-6006-100R	HOOD MIRROR, RH, BLACK, NON-HEATED
1	L59-6006-200	HOOD MIRROR, LH, CHROME, NON-HEATED
1	L59-6006-200R	HOOD MIRROR, RH, CHROME, NON-HEATED
4	W20-6011-06TDY0Z	NUT-HEX, M6 LOCKING

## Links

---

[22PBF Chassis List](#)

[22PBF Inspection and Repair Procedures](#)

[22PBF US Customer Letter](#)

[22PBF Canadian French Customer Letter](#)

[22PBF Canadian English Customer Letter](#)

## Revision History

---

**03/17/2023** - Changed take-off parts disposition from return to supplier to destroy 30 days after claim is paid.