

# <BULLETIN DRAFT>

22PBF

## 22PBF – 579 MLU Molded Hood Mirror Safety Recall

Author: Gunnar Nelson


2/7/2023

**Red Field Title:** Used in Recalls

**Purple Text** – KW Only (When Published to PACCARnet)

**Blue Text** – PB Only (When Published to PACCARnet)

**Black Text** – Applies to Both Divisions

|   |  |
|---|--|
| <b>Title</b> (metadata)                 | 22PBF - 579 MLU Molded Hood Mirror Safety Recall                                     |
|   | 22PBF - 579 MLU Molded Hood Mirror Safety Recall                                     |
| <b>Description</b>                      | 22PBF - 579 MLU Molded Hood Mirror Safety Recall                                     |
| <b>Bulletin No.</b>                     | 22PBF  |
| <b>Bulletin Category</b>                | Replacement Parts (Recall)   |
| <b>Supplier</b><br><i>(Recall Only)</i> | Velvac   |
| <b>Image</b>                            |  |
| <b>Service Subject</b>                  | 22PBF - 579 MLU Molded Hood Mirror Safety Recall                                     |
| <b>Section</b>                          | Cab - 02   |

# 22PBF - 579 MLU Molded Hood Mirror Safety Recall

|   |   |
|---|---|
| <b>What's New Abstract</b>                  | <p>Safety Recall - A mirror with a pivot joint break that does not have a wire harness or tether can result in foreign object debris on the roadway increasing the risk of a crash and/or injury.</p>   |
| <b>Revision</b>                             |   |
| <b>Condition / Complaint / Introduction</b> | <p>Certain model 579 MLU trucks equipped with molded hood mirrors may experience a mirror, pivot-joint failure. Within that population of trucks, there are mirrors that do not have a wire harness or tether to keep the upper half of the mirror with the truck if the pivot joint fails.</p> |
| <b>Chassis Affected / Situation</b>         | <p>PB – 2,995 (2,643 US and 430 CAN) model 579 MLU MY 2022-2023 with molded hood mirror.</p> <p>PPD – Component Sales – Chassis list by Engine Serial Number or EMY. Chassis VINs may not be available.</p>   |
| <b>Service Action / Resolution</b>          | <p><b>Safety Recall</b> - This bulletin will be updated when the repair procedure and parts are available.</p>  |
| <b>Warranty</b>                             |   |

# 22PBF - 579 MLU Molded Hood Mirror Safety Recall

---

|                   |  |
|-------------------|--|
| <b>Parts</b>      |  |
| <b>Background</b> | <p>KW Chassis List<br/>PB Chassis List</p> <p>KW US Customer Letter<br/>PB US Customer Letter</p> <p>KW Canada Customer Letter (English &amp; French)<br/>PB Canada Customer Letter (English &amp; French)</p> <p>Procedures Document (Shared KW &amp; PB)</p> |
| <b>Procedure</b>  |  |
| <b>Links</b>      |  |
| <b>Channels</b>   | <p>KWUS <input type="checkbox"/> KWCA <input type="checkbox"/> KWGS <input type="checkbox"/></p> <p>PBUS <input checked="" type="checkbox"/> PBCA <input checked="" type="checkbox"/></p> <p>Same bulletin published to KW &amp; PB regions? No</p>            |
| <b>Publish On</b> | 2/3/2023   |