

Safety Recall Notice Service Bulletin 517379 Rev. A



631 West 11th Street • P.O. Box 310 • Winamac, IN 46996

(574) 946-4139 • 1-800-THE-LIFT • www.braunability.com

February 2023

NHTSA Recall #: 23E014

Transport Canada Recall #: 2023-066

Applicable for

Component TAS-01223 | 225 CHILD SEAT WELDMENT

Included in the following kits:

Accessory Kit VSS-K-2603 | VSS-2600 (LS) CHILD LATCH KIT

Accessory Kit VSS-K-2604 | VSS-2600 (RS) CHILD LATCH KIT

This service bulletin details inspection of the child seat latch weldment (part number TAS-01223) and, if required, replacement of the child seat latch weldment.

Read Instructions Before Beginning

Labor Times

Inspection Only: 1/2 Hour

Inspection and Child Seat Latch Install: 1.5 Hours

Warranty Topics

Parts -> Recall -> 23E014 -> Inspect

Parts -> Recall -> 23E014 -> Repair

Inspect child seat latch. If the child seat latch is fully welded, as shown in Photo A, no further action is required.

If the child seat latch is not fully welded, as shown in Photo B, the child seat latch must be replaced. See instructions included in kit.

