OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23E-018

Manufacturer Name: AROW Global Corp

Submission Date: MAR 17, 2023

NHTSA Recall No.: 23E-018

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: AROW Global Corp

Address: 924 N Park View Circle

Mosinee WI 54455

Company phone: 6936020

Population:

Number of potentially involved: 1,500 Estimated percentage with defect: 100 %

Equipment Information:

Brand / Trade 1: AROW Global

Model: MV204

Part No.: MV2040000 Size: 40.83 x 40.10

Function: exit window

Descriptive Information: The recalled product is based on the manufacturing date and the unique

combination of size, glass type, window type, and customer. All part numbers with this combination have been identified and included. Approximately 1500 windows are affected and sold for use on New Flyer Industries transit busses

between 2011 and 2023

Production Dates: MAR 03, 2011 - MAR 06, 2023

Brand / Trade 2: AROW Global

Model: MV204

Part No.: MV2040001 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: NOV 08, 2013 - MAR 06, 2023

Brand / Trade 3: AROW Global

Model: MV204

Part No.: MV2040002 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: JAN 10, 2014 - MAR 06, 2023

Brand / Trade 4: AROW Global

Model: MV204

Part No.: MV2040005 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: FEB 25, 2014 - MAR 06, 2023

Brand / Trade 5: AROW Global

Model: MV204

Part No.: MV2040006 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: FEB 26, 2015 - MAR 06, 2023

Brand / Trade 6: AROW Global

Model: MV204

Part No.: MV2040007 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: JAN 24, 2017 - MAR 06, 2023

Brand / Trade 7: AROW Global

Model: MV207 Part No.: MV2070108

Size: 49.31 x 42.60 Function: exit window

Descriptive Information: *

Production Dates: AUG 09, 2019 - MAR 06, 2023

Brand / Trade 8: AROW Global

Model: MV204

Part No.: MV2040009 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: AUG 07, 2017 - MAR 06, 2023

Brand / Trade 9: AROW Global

Model: MV207

Part No.: MV2070049 Size: 49.31 x 42.60

Function: NR

Descriptive Information: *

Production Dates: FEB 14, 2013 - MAR 06, 2023

Brand / Trade 10: AROW Global

Model: MV207

Part No.: MV2070060 Size: 49.31 x 42.60

Function: NR

Descriptive Information: *

Production Dates: SEP 30, 2013 - MAR 06, 2023

Brand / Trade 11: AROW Global

Model: MV207

Part No.: MV2070092 Size: 49.31 x 42.60

Function: NR

Descriptive Information: *

Production Dates: OCT 19, 2016 - MAR 06, 2023

Brand / Trade 12: AROW Global

Model: MV207

Part No.: MV2070101 Size: 49.31 x 42.60

Function: exit window

Descriptive Information: *

Production Dates: JUN 01, 2018 - MAR 06, 2023

Brand / Trade 13: AROW Global

Model: MV204

Part No.: MV2040008 Size: 40.83 x 40.10

Function: NR

Descriptive Information: *

Production Dates: AUG 04, 2017 - MAR 06, 2023

Description of Noncompliance:

Description of the Specific emergency exit windows may not meet the passing criteria for FMVSS

Noncompliance: 571.217 S5.1.

FMVSS 1: 217 - Bus emergency exits and window retention and release

FMVSS 2: NR

Description of the Safety Risk: During a crash the emergency exit window latch may fail and allow the

window to open. Passenger retention during a vehicle crash may be reduced

and present and increase risk of passenger injury.

Description of the Cause: Window latch mechanism failed prior to reaching any passing criteria during

destructive testing. 75% of the force threshold was achieved at failure.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: AROW Global Corp

Address: 924 North Park View Circle

Mosinee Wisconsin 54455

Country: United States

Chronology:

NR

Description of Remedy:

Description of Remedy Program : A parts kit has been issued to correct the affected product. The parts kit

will be provided at no charge. Labor to install the parts kit will be

provided by AROW Global or compensation for labor based on an agreed

labor rate and time estimate.

How Remedy Component Differs A black plastic latch component will be replaced with an aluminum

from Recalled Component: component or a 2 latch assembly will be replaced with a 3 latch assembly.

Identify How/When Recall Condition The recall condition has been corrected in production in March 2023.

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: New Flyer Industries has been notified and they are processing

notifications to their vehicle owners

Planned Dealer Notification Date: MAR 06, 2023 - MAR 31, 2023 Planned Owner Notification Date: MAR 06, 2023 - MAR 31, 2023

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: New Flyer Industries

Address: NR

00

Country: NR Company Phone: NR

^{*} NR - Not Reported