



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

January 20, 2023

Mr. Charles Smart
Head of Claims Management Dept
Triumph Motorcycles America, Ltd.
Normandy Way
Hinckley LE10 3BZ

NEF-107DR
23V-006

Subject: Radiator Fan Motor May Fail and Cause Coolant Leak

Dear Mr. Smart:

This letter serves to acknowledge Triumph Motorcycles America, Ltd.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TRIUMPH/SPEED TRIPLE RR/2022-2023
TRIUMPH/SPEED TRIPLE RS/2022-2023

Mfr's Report Date: January 16, 2023

NHTSA Campaign Number: 23V-006

Components:

ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN

Potential Number of Units Affected: 1,351

Problem Description:

Triumph Motorcycles America, Ltd. (Triumph) is recalling certain 2022-2023 Speed Triple RS and Speed Triple RR motorcycles. The radiator fan may overheat, causing the fan motor to fail.

Consequence:

An inoperative fan motor can result in leaking or spraying hot coolant, increasing the risk of injury or crash.

Remedy:

Dealers will install an additional heatshield, free of charge. Owner notification letters are expected to be mailed February 1, 2023. Owners may contact Triumph's customer service at 1-678-854-2010. Triumph's number for this recall is SRAN 605.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the affected component(s). If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Triumph Motorcycles America, Ltd.'s contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is written in a cursive style with a checkmark at the end.

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement