



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 3, 2023

Mr. John Kobylarz
Safety Compliance Manager
Jaguar Land Rover North America, LLC
100 Jaguar Land Rover Way
Mahwah, NJ 07495

NEF-107ES
23V-044

Subject: Engine Cam Carrier May Leak Oil

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

LAND ROVER/DEFENDER/2023
LAND ROVER/DISCOVERY/2023
LAND ROVER/RANGE ROVER/2023
LAND ROVER/RANGE ROVER SPORT/2023
LAND ROVER/RANGE ROVER VELAR/2023

Mfr's Report Date: February 2, 2023

NHTSA Campaign Number: 23V-044

Components:

ENGINE AND ENGINE COOLING:ENGINE:OIL/LUBRICATION

Potential Number of Units Affected: 6,644

Problem Description:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2023 Range Rover, Range Rover Sport, Range Rover Velar, Discovery, and Defender vehicles. The engine cam carrier oil channel may be blocked, which can lead to an oil leak.

Consequence:

An oil leak in the presence of an ignition source can increase the risk of a fire.

Remedy:

Dealers will inspect and replace the engine cam carrier as necessary, free of charge. Owner notification letters are expected to be mailed March 31, 2023. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N763.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Jaguar Land Rover North America, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement