From: <u>Broadcast Messaging System</u>
To: <u>DL-BMS Message Monitors</u>

Subject: BMW Recall 23V-xxx: Digital Key - Interim Remedy is Available

Date: Thursday, February 23, 2023 1:47:42 PM

Publish Date: February 23, 2023 From: Technical Service Expiration Date: March 9, 2023 DCSnet Message Urgent



Subject: BMW Recall 23V-xxx: Digital Key - Interim Remedy is Available

Update as of today, February 23, 2023:

Interim remedy is now available and published in TIS under B84 01 23.

The interim solution is to remove the digital key card and it must be destroyed and disposed of. The customer must also sign a disclosure form before delivery of the vehicle. Please refer to the bulletin.

Remedy status will change to green (Remedy Available) tomorrow.

Sincerely,

Technical Service

Message from February 9, 2023:

BMW AG has issued a Delivery Stop (effective February 9, 2023) on certain Model Year 2022 – 2023 BMW vehicles that were produced between June 29, 2022 and February 16, 2023. This was originally called "Wireless Charging Tray".

As of February 17, 2023, this delivery stop has been upgraded to a Non-Compliance Recall.

Software in potentially affected vehicles may not recognize the removal of the digital key (key card or mobile phone) from the wireless charging tray, and therefore may not meet a Federal requirement.

The Recall Notice and Q&A have been attached for further information.

Sincerely,

Technical Service

Attachments:

No Attachments

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel

BMW Passenger Cars, CC-All

From: <u>Broadcast Messaging System</u>
To: <u>DL-BMS Message Monitors</u>

Subject: BMW Recall 23V-xxx: Reset Vehicle Data (BDC)

Date: Thursday, February 23, 2023 12:28:46 PM

Publish Date: February 23, 2023 From: Technical Service Expiration Date: March 9, 2023 DCSnet Message Urgent



Subject: BMW Recall 23V-xxx: Reset Vehicle Data (BDC)

BMW AG is conducting a Voluntary Safety Recall (effective February 23, 2023) on certain Model Year 2022 - 2023 BMW vehicles that were produced between September 8, 2021 and December 2, 2022.

During a dealer service visit, in which the Body Domain Controller (BDC) was replaced, a necessary vehicle programming and coding update may not have occurred. If this happened, the Automatic Door Lock (ADL) function would no longer be set to "default on". This could lead to an unlocked door condition which, in certain severe crashes, could allow a door to open.

The Recall Notice and Q&A have been attached for further information.

The bulletin will be updated next week.

Sincerely,

Technical Service

Attachments:

B610423 Recall Notice[1677173182897].pdf

B610423[1677173182897].pdf

B610423_23V-xyz-BDC-FAQ-(23Feb2023)[1677173182897].pdf B610423

Recall Notice[1677173182897].pdf B610423[1677173182897].pdf

B610423 23V-xyz-BDC-FAQ-(23Feb2023)[1677173182897].pdf

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel

BMW Passenger Cars, CC-All