

T-23-01 Safety Recall DEX Alert and STOP Post

DEX Alert

Group: Alerts / Recall

Start Date: 3/3/2023

Removal Date: 6/3/2023

Title: Safety Recall T-23-01 Released

Alert Text:

Polaris has determined that on some Model Year 2022-23 Slingshot vehicles, the alternator may have been improperly manufactured by the supplier and an internal rotor segment may crack and separate during operation, posing a fire hazard and risk of serious injury. The affected population is less than 100 vehicles.

To resolve this concern, Polaris has developed a procedure to replace the alternator on affected units.

Click **HERE** to view T-23-01 Safety Recall

Click **HERE** to view FAQ

STOP Post

Title: Safety Recall T-23-01 Released

Posting Date: 3/3/2023

Removal Date: 6/3/2023

Alert Text:

Polaris has determined that on some Model Year 2022-23 Slingshot vehicles, the alternator may have been improperly manufactured by the supplier and an internal rotor segment may crack and separate during operation, posing a fire hazard and risk of serious injury. The affected population is less than 100 vehicles.

 Click here: T-23-

01

Click here: T-23-01 Dealer FAQ