

Trouble viewing this email? [Open it in your browser >](#)



Date: March 3, 2023

Attn: All Dealership Personnel

Subject: Safety Recall T-23-01 Released

IMPORTANT SAFETY RECALL NOTICE

Stop Sale

IMPORTANT STOP SALE / STOP RIDE NOTICE!
Stop selling and riding affected vehicles immediately.

Safety Recall T-23-01

Polaris has determined that on some Model Year 2022-23 Slingshot vehicles, the alternator may have been improperly manufactured by the supplier and an internal rotor segment may crack and separate during operation, posing a fire hazard and risk of serious injury. The affected population is less than 100 vehicles.

To resolve this concern, Polaris has developed a procedure to replace the alternator on affected units. Please refer to the links below for complete information.

Special Service Tool required: Stretch Belt Installation Tool (commercially available, such as OEM Tools 24388, OTC 7425).



[View T-23-01 Safety Recall](#)

[View FAQ](#)

What Dealers Should Do?

As of March 03, 2023, **YOU MUST NOT SELL OR DELIVER** any **NEW OR USED Model Year 2022-2023 Slingshot** vehicles until it is repaired according to the **Safety Recall**.

Dealers are directed to inform affected consumers of the recall during any routine service repair and to implement the repair remedy.

Affected Units

2022 Slingshot R / S / SL / SLR
2023 Slingshot R / S / SL

Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Polaris Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

Thank you for your cooperation in this matter.

Sincerely,

Polaris Service