Manufacturer Name : Forest River, Inc. Submission Date : APR 21, 2023 NHTSA Recall No.: 23V-286 Manufacturer Recall No.: 51-1626

Manufacturer Information :

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Population :

Number of potentially involved : 1,381 Estimated percentage with defect : 100 %

Vehicle Information :

The information contained in this report was submitted pursuant to 49 CFR §573



23V-286

23V-286

Page 2

	On April 13, 2023, Forest River's Office of Corporate Compliance ("OCC") was notified
	by Cummins Onan of their equipment recall 23E030. On April 17, 2023, OCC received sales records and shipment location(s) and date(s) of the generators affected by Cummins Onan Recall 23E030. This data was used to identify the scope of affected vehicles. 2021 GALLERIA GAB24AM 18 2021 GALLERIA GAB24FLM 34 2021 GALLERIA GAB24FLM 34 2021 GALLERIA GAB24QM 54 2021 GALLERIA GAB24QM 54 2021 GALLERIA GAB24QM 54 2021 GALLERIA GAB24TM 17 2021 GALLERIA GAB24TM 17 2022 GALLERIA GAB24TM 2 2022 GALLERIA GAB24TM 2 2022 GALLERIA GAB24FLM 22 2022 GALLERIA GAB24FLM 22 2022 GALLERIA GAB24FLM 22 2022 GALLERIA GAB24FLM 25 2022 GALLERIA GAB24QM 25 2022 GALLERIA GAB24QM 4X 13 2022 GALLERIA GAB24QM 4X 13 2022 GALLERIA GAB24TM 8 2023 GALLERIA GAB24FLM 4 2023 GALLERIA GAB24FLM 4 2023 GALLERIA GAB24FLM 15 2023 GALLERIA GAB24FLM 4X14 2023 GALLERIA GAB24QM 30 2023 GALLERIA GAB24QM 4X 19 2023 GALLERIA GAB24TM 10 2023 GALLERIA GAB24TM 47 Total 344
VIN Range 1:	JUN 12, 2020 - APR 11, 2023 Begin : NR End : NR
VIN Range 1:	Begin : NK End : NK 🗌 Not sequential

The information contained in this report was submitted pursuant to 49 CFR \$573

23V-286

Page 3

Descrij	Body Style : Power Train :	NR On April 13, 20)23, Forest Rive	er's Office	of Corporate Com	
Descrij	Power Train :	NR On April 13, 20			of Corporate Com	
Descrij		On April 13, 20			of Corporate Com	
Descrij	ptive Information :				of Corporate Com	
		On April 13, 2023, Forest River's Office of Corporate Compliance ("OCC") was notified by Cummins Onan of their equipment recall 23E030.				
		the generators identify the sci 2021 NOVA 2021 NOVA 2021 NOVA 2022 NOVA 2022 NOVA 2022 NOVA 2023 NOVA 2023 NOVA	affected by Cu ope of affected NAB20C NAB20RB NAB20RBM NAB20C NAB20RB NAB20RBM NAB20C NAB20D NAB20D NAB20RB	mmins On	-	nt location(s) and date(s) o This data was used to
	Production Dates :	JUN 29, 2020 -	APR 06, 2023			
	VIN Range 1:	Begin :	NR	End :	NR	Not sequential

23V-286

Page 4

venicie a	2021-2023 Forest R	River Inc. Coachmen Beyond Class B Re	creational Vehicles
	BUSES, MEDIUM & I	0	
Body Style			
Power Train			
	 On April 13, 2023, F by Cummins Onan of On April 17, 2023, C the generators affect identify the scope of 2021 BEYOND 2021 BEYOND 2021 BEYOND 2021 BEYOND 2021 BEYOND 2021 BEYOND 	BYB22CAWD 75 BYB22CRWD 21 BYB22DAWD 39 BYB22DRWD 12 BYB22RBAWD 15 BYB22RBRWD 6	nt location(s) and date(s) o
Production Dates	2022BEYOND2022BEYOND2022BEYOND2022BEYOND2023BEYOND2023BEYOND2023BEYOND2023BEYOND2023BEYOND2023BEYOND2024BEYOND2025BEYOND2026MAR	BYB22CAWD 51 BYB22CRWD 2 BYB22DAWD 36 BYB22DRWD 2 BYB22RBAWD 16 BYB22CAWD 45 BYB22DAWD 28 BYB22RBAWD 20	
VIN Range 1	JUN 06, 2020 - MAR Begin : NI		☐ Not sequential

The information contained in this report was submitted pursuant to 49 CFR \$573

23V-286

Page 5

	2021-2023 Forest Rive BUSES, MEDIUM & HE		Class C Motorhomes	
Power Train :				
			e of Corporate Compliance recall 23E030.	("OCC") was notified
		d by Cummins O ffected vehicles. FRC2371AFT FRC2371FT FRC2381AFT FRC2381FT FRC2371AFT FRC2381AFT FRC2381AFT FRC2381FT FRC2381FT	records and shipment locat nan Recall 23E030. This da 1 2 1 4 2 6 5 1 2	
	JAN 19, 2021 - OCT 18			
VIN Range 1:	Begin : NR	End :	NR	Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573

23V-286

Page 6

venicie 5:	2021-2023 Forest River Inc.	Sunseeker Class C Motorh	omes
	BUSES, MEDIUM & HEAVY V		
Body Style :			
Power Train :	NR		
Descriptive Information :	On April 13, 2023, Forest Riv by Cummins Onan of their eq		ompliance ("OCC") was notified
Production Dates :	the generators affected by Cr identify the scope of affected 2021 SUNSEEKER SSC2 2021 SUNSEEKER SSC2 2022 SUNSEEKER SSC2 2022 SUNSEEKER SSC2 2022 SUNSEEKER SSC2 2022 SUNSEEKER SSC2 2022 SUNSEEKER SSC2 2023 SUNSEEKER SSC2	ummins Onan Recall 23E0 1 vehicles. 370FT 3 380AFT 3 380FT 4 370AFT 2 370FT 3 380AFT 7 380FT 5 370FT 1 380FT 3	ment location(s) and date(s) o 30. This data was used to
VIN Range 1:		End: NR	☐ Not sequential
Description of Defect :			
Description of Defect :			
-	ect : According to Cummins O fuel filter and the Injectio force, possibly resulting i	on Pump Module (IPM) mag	
Description of the Defe	fuel filter and the Injection	on Pump Module (IPM) mag	
Description of the Defe FMVSS	fuel filter and the Injection force, possibly resulting i	on Pump Module (IPM) mag	
Description of the Defe FMVSS FMVSS	fuel filter and the Injection force, possibly resulting in 51: NR 52: NR sk: According to Cummins O	on Pump Module (IPM) ma in a gasoline leak."	y have inadequate clamp
Description of the Defe FMVSS FMVSS Description of the Safety Ri	fuel filter and the Injection force, possibly resulting in 51: NR 52: NR sk: According to Cummins O	on Pump Module (IPM) may in a gasoline leak." nan Recall 23E030: "A gase increase the risk of fire." nan Recall 23E030: "The ca	y have inadequate clamp bline leak in the presence
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr	fuel filter and the Injection force, possibly resulting in 51: NR 52: NR sk: According to Cummins O of an ignition source may use: According to Cummins O	on Pump Module (IPM) may in a gasoline leak." nan Recall 23E030: "A gase increase the risk of fire." nan Recall 23E030: "The ca of the fuel hose."	y have inadequate clamp oline leak in the presence ause of the issue is an
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr	 fuel filter and the Injection force, possibly resulting in S 1 : NR S 2 : NR sk : According to Cummins O of an ignition source may use : According to Cummins O inadequate specification According to Cummins O 	on Pump Module (IPM) may in a gasoline leak." nan Recall 23E030: "A gase increase the risk of fire." nan Recall 23E030: "The ca of the fuel hose."	y have inadequate clamp oline leak in the presence ause of the issue is an

The information contained in this report was submitted pursuant to 49 CFR §573

23V-286

Page 7

Component Name 1:	CUMMINS POWER GENERATION
Component Description :	ONAN QG 2800i
Component Part Number :	2.8HGLAA-8302A

Component Name 2 : CUMMINS POWER GENERATION Component Description : ONAN QG 2800i EVAP Component Part Number : 2.8HGKAA-8303A

Supplier Identification :

Component Manufacturer

Name : Cummins, INC. Address : PO BOX 3005 COLUMBUS Indiana 47202-3005 Country : United States

Chronology :

On April 13, 2023, Forest River's Office of Corporate Compliance ("OCC") was notified by Cummins Onan of their equipment recall 23E030.

On April 17, 2023, OCC received sales records and shipment location(s) and date(s) of the generators affected by Cummins Onan Recall 23E030. This data was used to identify the scope of affected vehicles.

On April 21, 2023, Forest Rivers Corporate Recall Committee was informed of the equipment recall and filed a 573 report for vehicles affected.

Page 8

Description of Remedy :

Description of Remedy Program :	Forest River and Cummins will work together and will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer or Cummins/Onan service center will need to perform the remedy. The remedy is to inspect and, if the unit has the defect, to replace the subject fuel hose and associated clamps.
	What is the Forest River Customer Service Phone Number? Sunseeker (574) 206-7600 Coachmen Class B (574) 825-8602
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	OCC Forest River, Inc. Attn: WARRANTY MANAGER PO Box 30 Middlebury, IN 46540
	According to Cummins Onan Recall 23E030 "The remedy fuel hose has a unique part number A073T925."
	According to Cummins Onan Recall 23E030, "Production began with the remedy fuel hose on $02/21/2023$."
Recall Schedule :	

Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal
	NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement
	Letter.
Planned Dealer Notification Date :	MAY 23, 2023 - MAY 23, 2023
Planned Owner Notification Date :	MAY 23, 2023 ⁻ MAY 23, 2023

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573