

Trouble viewing this email? [Open it in your browser >](#)



Date: July 7, 2023

Attn: All Dealership Personnel

Subject: STOP SALE T-23-03 Released

IMPORTANT SAFETY NOTICE

Stop Sale

IMPORTANT STOP SALE NOTICE!
Stop selling and riding affected vehicles immediately.

Stop Sale T-23-03

Polaris Industries Inc. is issuing a stop sale notice to affected dealers relating to certain Model Year 2020-2023 Slingshot vehicles updated with Ride Command software SLS7AB. M32304A (released April 2023), after shifting out of reverse, the rear camera image may freeze and the rear camera image may not be displayed if shifted to reverse again.

Polaris is currently evaluating a repair procedure for this concern and will provide an update to dealers in the coming days.

[View T-23-03 Stop Sale](#)

[View T-23-03 FAQ](#)

What Dealers Should Do?

As of July 07, 2023, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED Model Year 2020-2023 Slingshot** until it is inspected or repaired according to the Safety Recall bulletin.

Affected Units

2020 - 2023 Slingshot

Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Polaris Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

Thank you for your cooperation in this matter.

Sincerely,

Polaris Service