



STOP SALE

Release Date: July 07, 2023

SLI

Communication #: T-23-03

Model Year(s): 2020–2023

— Confidential and Proprietary —

VERSION: R01 (July 07, 2023)

IMPORTANT STOP SALE NOTICE!
Stop selling affected vehicles immediately.

SUBJECT: REVERSE CAMERA

PURPOSE

Polaris has determined that on Model Year 2020-2023 Slingshot vehicles updated with Ride Command software SLS7AB. M32304A (released April 2023), after shifting out of reverse, the rear camera image may freeze and the rear camera image may not be displayed if shifted to reverse again.

Polaris is currently evaluating a repair procedure for this concern and will provide an update to dealers in the coming days.

AFFECTED MODELS

MODEL YEAR	MODELS	AFFECTED RANGE
2020–2023	All Slingshot Models	Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

CUSTOMER NOTIFICATION

When repair details are available, Polaris will notify consumers by letter (and email if available) immediately and follow-up with additional repair plans. At that time, dealers should also contact owners of affected VINs / PINs to inform them of this announcement.

CONTACT POLARIS

If you have questions that are not addressed in this document, contact Polaris Service through Ask Polaris or by phone at 800-330-9407 (US/Canada Dealers Only).

DEALER - WHAT TO DO?

As of July 07, 2023, **YOU MUST NOT SELL OR DELIVER** any **NEW OR USED Model Year 2020-2023 Slingshot models** affected by this **Stop Sale** until it is repaired according to the **Safety Recall**.